

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
 Governor

David Martin
 Cabinet Secretary

Tony Delfin
 Deputy Cabinet Secretary

David Catanach, Director
 Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

09-Aug-16

RAY WESTALL OPERATING, INC.
 P. O. BOX 4
 LOCO HILLS NM 88255

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

| FEDERAL N No.001 | | | | N-26-18S-30E | 30-015-20608-00-00 | | |
|--------------------------------|------------------------|---|-------------------|-------------------------------------|----------------------------------|-----------------------|--|
| Inspection Date | Type Inspection | Inspector | Violation? | *Significant Non-Compliance? | Corrective Action Due By: | Inspection No. | |
| 08/09/2016 | Routine/Periodic | Tony Morales | Yes | No | 11/12/2016 | ITM1622232520 | |
| Violations | | General Housekeeping (Rule 114) | | | | | |
| Comments on Inspection: | | OK. All Equipment and Location in Good Shape. PJO OLD TANK BATTERY ON LOCATION TANK BATTERIES NO SECONDARY IMPERMIABLE CONTAINMENT-BERM | | | | | |

| FEATHERSTONE FEDERAL No.001 | | | | F-26-18S-30E | 30-015-25440-00-00 | | |
|------------------------------------|------------------------|---|-------------------|-------------------------------------|----------------------------------|-----------------------|--|
| Inspection Date | Type Inspection | Inspector | Violation? | *Significant Non-Compliance? | Corrective Action Due By: | Inspection No. | |
| 08/09/2016 | Routine/Periodic | Tony Morales | Yes | No | 11/12/2016 | ITM1622233397 | |
| Violations | | Tank Battery Equipment (Rules 114, 115) General Housekeeping (Rule 114) | | | | | |
| Comments on Inspection: | | OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELL HEAD. TANK BATTERIES CONTAINMENT NOT COMPLETELY AROUND BATTERIES NO WINDSOCK NO PLACARDS STAINING AROUND DRAINS | | | | | |

FEATHERSTONE FEDERAL No.002

E-26-18S-30E

30-015-25620-00-00

| Inspection Date | Type Inspection | Inspector | Violation? | *Significant Non-Compliance? | Corrective Action Due By: | Inspection No. |
|-----------------|------------------|--------------|------------|------------------------------|---------------------------|----------------|
| 08/09/2016 | Routine/Periodic | Tony Morales | Yes | No | 11/12/2016 | iTM1622233965 |

Violations
General Housekeeping (Rule 114)

Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD

FEATHERSTONE FEDERAL No.003

D-26-18S-30E

30-015-25673-00-00


| Inspection Date | Type Inspection | Inspector | Violation? | *Significant Non-Compliance? | Corrective Action Due By: | Inspection No. |
|-----------------|------------------|--------------|------------|------------------------------|---------------------------|----------------|
| 08/09/2016 | Routine/Periodic | Tony Morales | Yes | No | 11/12/2016 | iTM1622235689 |

Violations
Tank Battery Equipment (Rules 114, 115)
General Housekeeping (Rule 114)

Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD STAINED AREA APPROX 15' X 30' AND LOCATION STAINING TANK BATTERY NO PLACARDS

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By;" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.