

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

AUG 29 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1624352162

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC 217955	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	COPPERHEAD 30 FEE #001H	Facility Type:	Tank Battery

Surface Owner:	Private	Mineral Owner:		API No.	30-015-39542
----------------	---------	----------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	30	26S	29E	480'	North	480'	East	Eddy

Latitude 32.0195389 Longitude 104.0167313

NATURE OF RELEASE

Type of Release:	Oil & Produced Water	Volume of Release:	5bbls of Oil & 30bbls of Produced Water	Volume Recovered:	4bbls of Oil & 26bbls of Produced Water
Source of Release:	FWKO	Date and Hour of Occurrence:	8/26/2016 1:30 pm	Date and Hour of Discovery:	8/26/2016 1:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Bratcher - NMOCD / Ms. Groves - SLO		
By Whom?	Robert Grubbs Jr.	Date and Hour:	Mon 8/29/2016 12:32 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A gasket failed on a FWKO. Replaced the gasket with a high-pressure gasket.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:	
Title:	Senior Environmental Coordinator	Approval Date:	8/30/16
E-mail Address:	rgrubbs@concho.com	Expiration Date:	N/A
Date:	August 29, 2016	Phone:	432-683-7443
		Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO. <u>2130116</u> LATER THAN: <u>8/30/16</u>	

* Attach Additional Sheets If Necessary

2RP-3851