

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 06 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
**RECEIVED** accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1425130938** **210737** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Amy Ruth	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: JRU #012H	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-22162

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	22S	30E	1600	North	2100	East	Eddy

Latitude 32.380535° Longitude -103.884395°

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	65 bbl	Volume Recovered	50 bbl
Source of Release	Jet Pump Suction Line	Date and Hour of Occurrence	8/26/2016 time unknown	Date and Hour of Discovery	8/26/2016 6:20 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Heather Patterson (NMOCD), Shelly Tucker (BLM)		
By Whom?	Amy Ruth	Date and Hour	8/26/2016 at 7:15 pm by email		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

The 4" poly suction line for the jet pump ruptured. The lease operator shut down the charge pump and isolated the valves. The section of line was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The leak affected approximately 7,000 square feet of caliche pad and was prevented from entering the pasture due to the berms surrounding the drill island. Vacuum trucks recovered standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth	Signed By  Approved by Environmental Specialist:	
Title: EHS Remediation Specialist	Approval Date: 9/6/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: <b>O.C.D. Rules &amp; Guidelines</b> <b>REMEDIAL PROPOSAL NO</b> Attached <input type="checkbox"/>	
Date: 9/1/2016 Phone: 432-661-0571	<b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN: 10/8/16</b>	

\* Attach Additional Sheets If Necessary

2RD-3864