

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
Form C-141
Revised August 8, 2011
SEP 20 2016
Submit 1 copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1626638297

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>1010910</i>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cedar Canyon 22-15 Fee #31H	Facility Type	Well

Surface Owner	BLM	Mineral Owner		API No.	30-015-43809
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	22	24S	29E					Eddy County, NM

Latitude N 32.20724° Longitude W 103.97523°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	30 bbls oil, 30 bbls produced water	Volume Recovered	55 bbls
Source of Release	Tank spill due to operator error	Date and Hour of Occurrence	09/04/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD, Shelly Tucker- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/06/2016	<i>*4:10pm (e-mail)</i>	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Operator error caused and tank to spill 30 bbls of oil and 30 bbls of produced water onto location. A vacuum truck recovered 55 bbls of fluids and the error was corrected.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 100' x 80' on the location pad. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Casey Summers	Approved by Environmental Specialist:	
Title:	NM Environmental Advisor	Approval Date:	<i>9/22/16</i> Expiration Date: <i>NIA</i>
E-mail Address:	Casey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	<i>9-20-16</i> Phone: (575) 513-8289	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary
LATER THAN: 10/26/16 *2RP-3898*