

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

SEP 26 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

**NAB1627152334**

**OPERATOR**

☒ Initial Report ☒ Final Report



Name of Company: Chevron USA Inc. <b>4323</b>	Contact: Josepha DeLeon	
Address: 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: 575-263-0424	
Facility Name: Brushy 12 Federal No. 001	Facility Type: Oil Well	
Surface Owner: Federal	Mineral Owner	API No.: 30-015-25416

**LOCATION OF RELEASE**

Unit Letter N	Section 12	Township 26S	Range 29E	Feet from the 560	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.051010 Longitude: 103.9384

**NATURE OF RELEASE**

Type of Release: Spill	Volume of Release: 2.97 BO 11.87 BW	Volume Recovered: 2.97 BO 11.87 BW
Source of Release: Water tank overflow	Date and Hour of Occurrence: 08/26/2016 10:00 AM	Date and Hour of Discovery: 08/26/2016 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson - NMOCD Jim Amos - BLM	
By Whom? Josepha DeLeon	Date and Hour: 08/26/2016: 01:40 PM	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.*  Water tank overflow to lined secondary containment. All fluid was recovered.		
Describe Area Affected and Cleanup Action Taken.*  Vaccum truck picked all fluid.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josepha DeLeon	Approved by Environmental Specialist: 	
Title: HES Specialist - Compliance Support, Environmental	Approval Date: 9/26/16	Expiration Date: N/A
E-mail Address: jdx@chevron.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: 09/08/2016	Phone: 575-263-0424	

\* Attach Additional Sheets If Necessary

2RP-3912