

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 26 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1627150011

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: Mewbourne Oil Company 14744		Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241		Telephone No. 575-393-5905	
Facility Name: Limousine 15 N #001		Facility Type: Oil Well	
Surface Owner: Private		Mineral Owner: N/A	
		API No. 30-015-36942	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	15	20S	25E	990'	South	1650'	West	Eddy

Latitude 32.568821 Longitude -104.4758148

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: estimated 10 bbls	Volume Recovered: 10 bbls
Source of Release: Fiberglass water tank	Date and Hour of Occurrence 9-16-16	Date and Hour of Discovery 9-16-16 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson	
By Whom? Robin Terrell	Date and Hour 9-16-16 3:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Upon being struck by lightning, one fiberglass water tank caught fire. Fire department was contacted to extinguish the fire. All released fluid was contained within lined secondary containment.		
Describe Area Affected and Cleanup Action Taken.* Affected area- All free standing fluid within lined secondary containment was recovered with a vacuum truck.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Z. Thomas</i>	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Rep.	Approval Date: <i>9/26/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 9-20-16 Phone: 575-602-2188		

* Attach Additional Sheets If Necessary

2RD-3911