NM OIL CONSERVATION

District I 1625 N. French Dr., Hobbs, NM 88240

ARTESIA DISTRICT

State of New Mexico

Form C-141 Revised August 8, 2011

Final Report

District II 811 S. First St., Artesia, NM 88210 OCT 05 2016 gy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

☐ Initial Report

District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Name of Company: Linn Energy

Oil Conservation Division RECEIVED 1220 South St. Francis Dr.

Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

Contact: EL Gonzales

Address: 2130 W Bender, Hobbs, NM 88240						Telephone No. 575-738-1739					
Facility Name: HE West B #071						Facility Type: Oil Producer					
Surface Owner: Federal Mineral Owner:					wner:	Federal			API No	API No. 30-015-28573	
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range			South Line	Feet from	East/	West Line	County	
I	9	17S	31E	1335		outh	15	1	West	Eddy	
								<u></u>			
Latitude: 32° 50' 42.30" N Longitude: 103° 51' 58.03" W											
NATURE OF RELEASE											
Type of Release: Oil							Volume of Release: 2 – 3 bbls Volume Recovered: 1 bbl				
Source of Release: Stuffing Box									Date and 01/06/201	and Hour of Discovery 6/2011	
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Required						If YES, To Whom? NMOCD					
						Date and Hour: 01/06/2011					
By Whom? Kimberly Wilson Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
☐ Yes ☐ No						11 125, Volume impacting the watercoarse.					
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.*											
Stuffing box leak. Removed contaminated dirt and exported. Re-packed stuffing box.											
Describe Area Affected and Cleanup Action Taken.											
The contaminated soil was removed from the site and properly disposed of at a NMOCD approved facility. The excavation was backfilled with clean,											
imported soil to ground surface and contoured to the surrounding area.											
										uant to NMOCD rules and	
										eases which may endanger	
										eve the operator of liability	
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
							OIL CON	ISERY	VATION	<u>DIVISION</u>	
Signature									1		
						Approved by Environmental Specialist:					
Printed Name: EL Gonzales						Approved by Environmental operation.					
Title: Production Supervisor A						Approval Date: 10/16/16 Expiration Date: N/A					
E-mail Addre	ess: <u>elgonza</u>	les@linnenerg	gy.com			Conditions o	f Approval:		Ŋ	Attached	
Date: 9/7/2016 Phone: 575-504-8002							· +	ne	ul		
Attach Addit	Attach Additional Sheets If Necessary 2P-590										
										-K1-J 7U	