

Tony Morales & Gilbert Cordero,

The violations on the attached documents have been resolved.

Thanks,

Tanner Riewe

Production Engineer

Office: (575) 393-5905

Cell: (575) 602-3009

Fax: (575) 393-7259

Email: triewe@mewbourne.com



NM OIL CONSERVATION
ARTESIA DISTRICT
NOV 07 2016

RECEIVED

11-8-16

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Tony Delfin
Deputy Cabinet Secretary

David Catanach, Director
Oil Conservation Division




Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

30-Sep-16

MEWBOURNE OIL CO
PO Box 5270
Hobbs NM 88241-8241


10-7-16

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

ZIRCON 2 EH STATE		No.001H	E-2-19S-29E		30-015-40572-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
09/30/2016	Routine/Periodic	Tony Morales	Yes	No	1/3/2017	iTM1627430638
Violations						
Surface Leaks/Spills						
General Housekeeping (Rule 114)						
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELLHEAD STAINED AREA APPROX 20' X 80' CONTAMINATED MATERIAL ON LOCATION POLYPIPE PIECES ON LOCATION TUBING JOINT ON LOCATION.				