

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 10 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB11031947928



| | | | | | |
|---|-------|-----------------------------|----------------------|--|---------------------------------------|
| Name of Company: COG Operating LLC 229137 | | OPERATOR | | <input checked="" type="checkbox"/> Initial Report | <input type="checkbox"/> Final Report |
| Address: 600 West Illinois Avenue, Midland TX 79701 | | Contact: Robert McNeill | | | |
| Facility Name: Colt State #4 SWD | | Telephone No. 432-683-7443 | | | |
| | | Facility Type: Tank Battery | | | |
| Surface Owner: | State | Mineral Owner: | API No. 30-015-41401 | | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| D | 05 | 25S | 28E | 1066 | North | 850 | West | Eddy |

Latitude Longitude

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release: Produced Water | Volume of Release: 75 bbls | Volume Recovered: 74 bbls |
| Source of Release: Tank Battery | Date and Hour of Occurrence: 11/7/2016 3:45 pm | Date and Hour of Discovery: 11/7/2016 3:45 pm |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? | Date and Hour: | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Two-Inch nipple on the bottom of the filter pot broke. Repaired the filter pot. | | |
| Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Robert Grubbs Jr. | Approved by Environmental Specialist:  | |
| Title: Senior HSE Coordinator | Approval Date: 11/14/16 | Expiration Date: N/A |
| E-mail Address: rgrubbs@concho.com | Conditions of Approval: | Attached <input checked="" type="checkbox"/> |
| Date: 11/11/2016 Phone: 432-683-7443 | | |

* Attach Additional Sheets If Necessary

2RP-3988