			N		ISERVAT		
			in an	: .	DISTRICT		asserbiosocia _.
				NOV 2	9 2016	· · ·	÷.,
listrict I 625 N. French Dr., Hobbs, NM 88240		New Mexic				Form	
listrict II 11 S. First St., Artesia, NM 88210	Energy Minerals	and Natural	Resources	REC	IVEN	Revised August	
<u>istrict III</u> 000 Rio Brazos Road, Aztec, NM 87410		vation Divin St. Franci		Submit I Co	by to appropri accordance w	iate District O ith 19.15.29 N	ffice in IMAC.
l <u>istrict IV</u> 220 S. St. Francis Dr., Santa Fe, NM 87505		e, NM 8750					
Je de la company de la comp	Release Notification	n and Co	rrective A	ction			
NAB1433455179		OPERAT	OR		tial Report	🔲 Final	Repor
		Contact:		Robert Mc			
Address: 600 West Illinois Avenue Facility Name: Skelly 605 Battery		Telephone N Facility Type		432-683-74	45	· ·	
		ruenny rype					
Surface Owner: Federal	Mineral Owner:			APIN	<u>lo. 30-0</u>	15-36885	· .
	LOCATIO						
	nge Feet from the North 1E 2460	South Line	Feet from the 2410	East/West Line East	:	County Eddy	
	· · · · · ·				•		· .
	Latitude 32.8341255	Longitud	e 103.839607	12		•••	
	NATURE	OF RELE	LASE	14. State 199			
Type of Release:		Volume of		Volum	Volume Recovered:		
Produced Wat Source of Release:	er	Date and H	6 bbls our of Occurrence	re Date ar	d Hour of Di	bis scovery:	· .
Flowline		11/2	3/2016 8:55 am			6 8:55 am	
Was Immediate Notice Given?	s 🛛 No 🖾 Not Required	If YES, To	Whom?				
By Whom?		Date and H	our:				
Was a Watercourse Reached?	es 🖾 No	If YES, Vo	lume Impacting	the Watercourse.		· ·	
If a Watercourse was Impacted, Describe F	fully.*	1					
	îully.*		· ·				•
If a Watercourse was Impacted, Describe F							
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial	Action Taken.*						
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had	Action Taken.* a hole in it. Replace the failed	connection.					
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility	Action Taken.* a hole in it. Replace the failed n Taken.* y. A vacuum truck was dispate	hed to remove	all freestanding	fluids. Concho v	rill have the sp	pill area evalu	atcd
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility for any possible impact from the release ar	Action Taken.* a hole in it. Replace the failed n Taken.* y. A vacuum truck was dispate	hed to remove	all freestanding the NMOCD for	fluids. Concho v r approval prior	vill have the s to any signific	pill area evalu cant remediation	ated on
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility	Action Taken.* a hole in it. Replace the failed n Taken.* y. A vacuum truck was dispate	hed to remove	all freestanding the NMOCD fo	fluids. Concho w r approval prior	vill have the sp to any signific	pill area evalu ant remediation	ated on
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Actio This release occurred within a lined facility for any possible impact from the release ar activities.	Action Taken.* a hole in it. Replace the failed on Taken.* y. A vacuum truck was dispate ad we will present a remediation above is true and complete to	thed to remove on work plan to the best of my	the NMOCD fo	r approval prior understand that p	to any signific	cant remediation	on . nd
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility for any possible impact from the release are activities.	Action Taken.* a hole in it. Replace the failed n Taken.* y. A vacuum truck was dispate id we will present a remediation above is true and complete to port and/or file certain release	hed to remove on work plan to the best of my notifications ar	he NMOCD fo knowledge and t	n approval prior understand that p ctive actions for	to any signific ursuant to NM releases which	cant remediation 10CD rules and h may endange	on . nd er
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility for any possible impact from the release are activities.	Action Taken.* a hole in it. Replace the failed in Taken.* y. A vacuum truck was dispate id we will present a remediation above is true and complete to port and/or file certain release is eptance of a C-141 report by the set of the set	thed to remove on work plan to the best of my notifications ar he NMOCD ma	the NMOCD for knowledge and to d perform corre- arked as "Final F	ir approval prior understand that p ctive actions for Report" does not	to any signific ursuant to NM releases which relieve the op	ant remediation 10CD rules and h may endange erator of liabil	nd er ity
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility for any possible impact from the release are activities. I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to adeq or the environment. In addition, NMOCD	Action Taken.* a hole in it. Replace the failed on Taken.* y. A vacuum truck was dispate id we will present a remediation above is true and complete to port and/or file certain release of eptance of a C-141 report by fluately untely investigate and remedia acceptance of a C-141 report	thed to remove on work plan to the best of my notifications ar he NMOCD ma ite contamination	the NMOCD for knowledge and t id perform corre arked as "Final F on that pose a th	ir approval prior understand that p ctive actions for Report" does not reat to ground wa	to any signific ursuant to NM releases which relieve the op- tter, surface w	ant remediation 10CD rules and h may endanger erator of liabil vater, human h	nd er ity calth
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility for any possible impact from the release ar activities. I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to adeq	Action Taken.* a hole in it. Replace the failed on Taken.* y. A vacuum truck was dispate id we will present a remediation above is true and complete to port and/or file certain release of eptance of a C-141 report by fluately untely investigate and remedia acceptance of a C-141 report	thed to remove on work plan to the best of my notifications ar he NMOCD ma ite contamination	the NMOCD for knowledge and t id perform corre- arked as "Final F on that pose a the e the operator of	ar approval prior understand that p ctive actions for Report" does not reat to ground wa responsibility fo	to any signific ursuant to NM releases which relieve the op tter, surface w r compliance	ant remediation 10CD rules and h may endanger erator of liabil vater, human h with any othe	nd er ity calth
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Action This release occurred within a lined facility for any possible impact from the release are activities. I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to adeq or the environment. In addition, NMOCD	Action Taken.* a hole in it. Replace the failed on Taken.* y. A vacuum truck was dispate id we will present a remediation above is true and complete to port and/or file certain release of eptance of a C-141 report by fluately untely investigate and remedia acceptance of a C-141 report	thed to remove on work plan to the best of my notifications ar he NMOCD ma ite contamination	knowledge and a ad perform corre- arked as "Final F on that pose a th c the operator of OIL CON	understand that p ctive actions for Report" does not reat to ground wa responsibility fo	to any signific ursuant to NM releases which relieve the op tter, surface w r compliance	ant remediation 10CD rules and h may endanger erator of liabil vater, human h with any othe	nd er ity calth
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Actio This release occurred within a lined facility for any possible impact from the release ar activities. I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to adeq or the environment. In addition, NMOCD federal, state, or local laws and/or regulations Signature: Water Amage State	Action Taken.* <u>a hole in it. Replace the failed</u> on Taken.* y. A vacuum truck was dispate ad we will present a remediation above is true and complete to port and/or file certain release the eptance of a C-141 report by the uately investigate and remediated acceptance of a C-141 report ons.	the best of my notifications ar he NMOCD ma the contamination does not relieve	he NMOCD for knowledge and n id perform corre- arked as "Final F on that pose a th the operator of <u>OIL CON</u> Signed	ar approval prior understand that p ctive actions for Report" does not reat to ground wa responsibility fo ISERVATIO By	to any signific ursuant to NM releases which relieve the op tter, surface w r compliance	ant remediation 10CD rules and h may endanger erator of liabil vater, human h with any othe	nd er ity calth
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Actio This release occurred within a lined facility for any possible impact from the release ar activities. I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to aded or the environment. In addition, NMOCD federal, state, or local laws and/or regulations Signature: KMCCA MAWUM Printed Name: Rebecca H	Action Taken.* <u>a hole in it. Replace the failed</u> on Taken.* y. A vacuum truck was dispate ad we will present a remediation above is true and complete to port and/or file certain release if eptance of a C-141 report by the uately investigate and remedia acceptance of a C-141 report of ons. 7 	the do remove on work plan to the best of my notifications an he NMOCD ma te contamination does not relieve Approved by	knowledge and n id perform corre- arked as "Final F on that pose a the e the operator of <u>OIL CON</u> Signed Environmental S	ar approval prior understand that p ctive actions for Report" does not reat to ground wa responsibility fo ISERVATIO By Mile By	to any signific ursuant to NM releases which relieve the op- nter, surface w r compliance N DIVISI	ant remediation 10CD rules and h may endanger erator of liabil vater, human h with any othe	nd er ity calth
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Actio This release occured within a lined facility for any possible impact from the release ar activities. I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to aded or the environment. In addition, NMOCD federal, state, or local laws and/or regulations Signature: Reference Hammed	Action Taken.* <u>a hole in it. Replace the failed</u> on Taken.* y. A vacuum truck was dispate ad we will present a remediation above is true and complete to port and/or file certain release if eptance of a C-141 report by the uately investigate and remedia acceptance of a C-141 report ons. 7 	the d to remove on work plan to the best of my notifications an he NMOCD ma te contamination does not relieve Approved by Approval Dat	knowledge and n hd perform corre- arked as "Final F on that pose a th e the operator of <u>OIL CON</u> Signed Environmental S e: 22	ar approval prior understand that p ctive actions for Report" does not reat to ground wa responsibility fo ISERVATIO By	to any signific ursuant to NM releases which relieve the op- nter, surface w r compliance N DIVISI	ant remediation 10CD rules and h may endanger erator of liabil vater, human h with any othe	nd er ity calth
If a Watercourse was Impacted, Describe F Describe Cause of Problem and Remedial Two-inch nipple after the water pump had Describe Area Affected and Cleanup Actio This release occurred within a lined facility for any possible impact from the release ar activities. I hereby certify that the information given regulations all operators are required to rep public health or the environment. The acc should their operations have failed to aded or the environment. In addition, NMOCD federal, state, or local laws and/or regulations Signature: KMCCA MAWUM Printed Name: Rebecca H	Action Taken.* <u>a hole in it. Replace the failed</u> on Taken.* y. A vacuum truck was dispate ad we will present a remediation above is true and complete to port and/or file certain release if eptance of a C-141 report by the uately investigate and remedia acceptance of a C-141 report ons. 7 	the do remove on work plan to the best of my notifications an he NMOCD ma te contamination does not relieve Approved by	knowledge and n hd perform corre- arked as "Final F on that pose a th e the operator of <u>OIL CON</u> Signed Environmental S e: 22	ar approval prior understand that p ctive actions for Report" does not reat to ground wa responsibility fo ISERVATIO By Mile By	to any signific ursuant to NM releases which relieve the op- nter, surface w r compliance N DIVISI	ACCD rules and h may endangerator of liabil vater, human h with any other ON	nd er ity calth

T