

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report



Name of Company <b>Stephens &amp; Johnson Operating Co.</b>	Contact <b>William M. Kincaid</b>
Address <b>P.O. Box 2249 Wichita Falls, Tx 76307-2249</b>	Telephone No. <b>(940) 723-2166</b>
Facility Name <b>Mobile 22 Federal No. 6</b>	Facility Type <b>Producing Oil Well</b>
Surface Owner: <b>J. G. Ross Jr.</b>	Mineral Owner <b>MMS (Federal)</b> Lease No. <b>NM-22634</b>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	22	26S	29E	2260	South	2310	West	Eddy

Latitude N 32.02667° Longitude W 103.97310°

**NATURE OF RELEASE**

Type of Release: <b>Stuffing box leak</b>	Volume of Release <b>2 bbls</b>	Volume Recovered <b>None</b>
Source of Release <b>Wellhead</b>	Date and Hour of Occurrence <b>10/14/09</b>	Date and Hour of Discovery <b>10/14/09</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  N/A		
Describe Cause of Problem and Remedial Action Taken.* Stuffing box leaked. To alleviate the problem, the packing within the stuffing box was replaced.		
Describe Area Affected and Cleanup Action Taken.* Area adjacent to wellhead where release occurred was scrapped and clean soils replaced on October 16, 2009. In addition, trenches were installed in order to delineate the site. On October 7, 2010, approximately 180 cubic yards of soil were excavated and transported offsite for disposal at Lea Land Inc. of Carlsbad, NM. The site was backfilled to within 4 feet and poly liners installed. Above the liner clean soils were brought in and placed to within 1 foot of the surface. Afterwards, a 1 foot thick caliche base was then installed over the soils.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>William M. Kincaid</b>	Approved by District Supervisor: 	
Title: <b>Petroleum Engineer</b>	Approval Date: <b>12/7/10</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>mkincaid@sjoc.net</b>	Conditions of Approval: 	Attached <input type="checkbox"/>
Date: <b>01/25/11</b>	Phone: <b>(940) 723-2166</b>	

\* Attach Additional Sheets If Necessary

288-357