

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

# NM OIL CONSERVATION

ARTESIA DISTRICT

OCT 27 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company LINN Energy	Contact EL GONZALES	
Address 2130 W BENDER HOBBS NM 88240	Telephone No. 575-738-1739	
Facility Name TURNER B 118	Facility Type OIL WELL E-FILE #710	
Surface Owner BLM	Mineral Owner BLM	API No. 30-015-28920 LEASE NO LC-029395B

### LOCATION OF RELEASE

Unit Letter M	Section 20	Township 17S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.8156 Longitude -103.9009

### NATURE OF RELEASE

Type of Release PRODUCED WATER / HYDROCARBONS	Volume of Release UNKNOWN	Volume Recovered UNKNOWN
Source of Release WELL HEAD / STUFFING BOX	Date and Hour of Occurrence	Date and Hour of Discovery FEB 11
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



#### Describe Cause of Problem and Remedial Action Taken

A release from the well head/stuffing box caused a release of fluid to leave the location and enter the pasture on the south side of the location and onto the lease road to the south/southwest of the location. The affected area is approximately 3' x 150' in each the pasture and the lease road. The affected area shows signs that remedial action had been taken, but not completed, the affected areas will be remediated and a work plan submitted to NM OCD and BLM for review and approval

#### Describe Area Affected and Cleanup Action Taken.\*

Delineation complete

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: E. L. Gonzales	Approved by Environmental Specialist: 	
Title: Production Supervisor Production Supervisor	Approval Date: 12/22/16	Expiration Date: N/A
E-mail Address: ELgonzales.linnenergy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date 9-7-16	Phone: 505-504-8002	

\* Attach Additional Sheets If Necessary

22P-710