## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

**Tony Delfin** Acting Cabinet Secretary David R. Catanach, Division Director Oil Conservation Division



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

26-Jan-17

## LARRY MARKER DBA MARKER OIL PO BOX 3188 Roswell NM 88202-8202

## **LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

|   |  | INSPECTIO   | N DETAII   | SECTION   |  |                      |
|---|--|---|------------|---|--|----------------------|
| NORTH SQUARE LAKE UNIT No.012<br>Inspection<br>Date Type Inspection |  | lo.012<br>Inspector                               | Violation? | P-19-16S-31E<br>*Significant<br>Non-Compliance? | 30-015-04856-00-<br>Corrective<br>Action Due By: | 00<br>Inspection No. |
| 01/26/2017  | Routine/Periodic<br>Violations<br>Absent Well Identification S | Tony Morales                                      | Yes        | No  | 5/1/2017   | iTM1702647655        |
| Comments  | on Inspection: OK. All   | Equipment and Location in DNNECTED                | Good Shape | . LOCTION SIGN N                                | OT VISIBLE. FLOW                                 | LINE                 |
| NORTH SQ  | UARE LAKE UNIT N   | lo.007  |            | J-20-16S-31E <b>30-015-04863-00-00</b>          |  |                      |
| Inspection<br>Date  | Type Inspection  | Inspector   | Violation? | *Significant<br>Non-Compliance?                 | Corrective<br>Action Due By:                     | Inspection No.       |
| 01/26/2017  | Routine/Periodic<br>Violations<br>Surface Leaks/Spills         | Tony Morales                                      | Yes        | No  | 5/1/2017   | iTM1702649124        |
| Comments  |  | Equipment and Location in NG APPROX. 10' X 30' FR | •          | . PJ STAINING AR                                | OUND WELL HEAD                                   |                      |

|                               | UARE LAKI         | E UNIT No.097  |                                     | D-31-16S-31E                           | 30-015-04942-00-00                     |                              |                   |  |  |
|-------------------------------|-------------------|--|-------------------------------------|--|--|------------------------------|-------------------|--|--|
| Inspection<br>Date            | Type Inspectio    | n  | Inspector                           | Violation?                             | *Significant<br>Non-Compliance?        | Corrective<br>Action Due By: | Inspection No.    |  |  |
| 01/26/2017                    | Routine/Perio     | odic   | Tony Morales                        | Yes                                    | No                                     | 5/1/2017                     | iTM1702640541     |  |  |
|                               | Violations        |  | -                                   |  |  |                              |                   |  |  |
|                               | Absent Well Ide   | ntification Signs (R   | ule 103)                            |  |  |                              |                   |  |  |
| Comments                      | on Inspection:    | OK. All Equipr<br>VISIBLE.   | nent and Location ir                | n Good Shape                           | . PJ POWER OFF L                       | OCATION SIGN NO              | Г                 |  |  |
| NORTH SQ                      | UARE LAKI         | E UNIT No.142  |                                     | E-31-16S-31E <b>30-015-20184-00-00</b> |  |                              |                   |  |  |
| Inspection<br>Date            | *                 |  | Inspector                           |  | *Significant<br>Non-Compliance?        | Corrective                   | Inspection No.    |  |  |
| 01/26/2017                    | Routine/Peri      |  | Tony Morales                        | Violation?<br>Yes                      | Non-Comphance:<br>No                   | Action Due By:<br>5/1/2017   | iTM1702640168     |  |  |
| 01/20/2017                    | Violations        | Juie   | Tony Morales                        | 1 65                                   | NO                                     | 5/1/2017                     | 11111/02040108    |  |  |
|                               |                   | ntification Signs (R   | (ule 103)                           |  |  |                              |                   |  |  |
| Comments                      | on Inspection:    | •  |                                     | 1 Good Shape                           | . LOCATION SIGN                        | NOT VISIBLE.                 |                   |  |  |
|                               |                   | E UNIT No.162  |                                     |  | 0-31-16S-31E                           | 30-015-24457-00-             | 00                |  |  |
| Inspection                    | -                 |  |                                     |  | *Significant                           | Corrective                   |                   |  |  |
| Date                          | Type Inspectio    |  | Inspector                           | Violation?                             | Non-Compliance?                        | Action Due By:               | Inspection No.    |  |  |
| 01/26/2017                    | Routine/Peri      | odic   | Tony Morales                        | Yes                                    | No                                     | 5/1/2017                     | iTM1702638436     |  |  |
|                               | Violations        |  |                                     |  |  |                              |                   |  |  |
| <b>a</b> <i>i</i>             |                   | ntification Signs (R   |                                     | <b>A 1 4</b>                           |  |                              |                   |  |  |
| Comments                      | on Inspection:    |  | nent and Location in GN NOT VISIBLE | n Good Shape                           | . PJ. POWER OFF N                      | O ELECTRICAL MO              | DTOR              |  |  |
| NORTH SQUARE LAKE UNIT No.159 |                   |  |                                     |  | L-31-16S-31E <b>30-015-24706-00-00</b> |                              |                   |  |  |
| Inspection<br>Date            | Type Inspectio    | m  | Inspector                           | Violation?                             | *Significant<br>Non-Compliance?        | Corrective<br>Action Due By: | Inspection No.    |  |  |
| 01/26/2017                    | Routine/Peri-     | odic   | Tony Morales                        | Yes                                    | No                                     | 5/1/2017                     | iTM1702638052     |  |  |
|                               | Violations        |  |                                     |  |  |                              |                   |  |  |
|                               |                   | eeping (Rule 114)  |                                     |  |  |                              |                   |  |  |
| Comments                      | on Inspection:    |  | nent and Location in TED MATERIAL N |  | E. PJ STAINING ARG<br>ELL HEAD         | OUND WELL HEAD.              |                   |  |  |
| NORTH SQUARE LAKE UNIT No.198 |                   |  |                                     |  | O-19-16S-31E 30-015-33047-00-00        |                              |                   |  |  |
| Inspection                    |                   |  | Turn of                             |  | *Significant                           | Corrective                   | Teres addiese Nie |  |  |
| Date                          | Type Inspectio    |  | Inspector                           | Violation?                             | Non-Compliance?                        | Action Due By:               | Inspection No.    |  |  |
| 01/26/2017                    | Routine/Peri      | odic   | Tony Morales                        | Yes                                    | No                                     | 5/1/2017                     | iTM1702647425     |  |  |
|                               | Violations        |  |                                     |  |  |                              |                   |  |  |
|                               |                   | eeping (Rule 114)  |                                     | 0 10                                   |  |                              | D                 |  |  |
| Comments                      | on Inspection:    |  | BOX ON LOCATI                       | e. PJO. STAINING A                     | ROUND WELL HEA                         | \D.                          |                   |  |  |
| NORTH SQ                      | <b>)UARE LAKI</b> | E UNIT No.199  | )                                   |  | A-30-16S-31E                           | 30-015-33068-00-             | 00                |  |  |
| Inspection                    |                   |  | Inspector                           | Violation?                             | *Significant                           | Corrective                   | Inspection No.    |  |  |
| Date<br>01/26/2017            |                   |  | Tony Morales                        | Yes                                    | Non-Compliance?                        | Action Due By:               | -                 |  |  |
| 01/20/2017                    | Violations        | ouic   | rony morates                        | 105                                    | No                                     | 5/1/2017                     | iTM1702648115     |  |  |
|                               |                   | lentification Signs (Rule 103)   |                                     |  |  |                              |                   |  |  |
|                               | General Housek    |  |                                     |  |  |                              |                   |  |  |
| Comments on Inspection:       |                   | OK. All Equipment and Location in Good Shape. PJ. OLD TUBING ON LOCATION.<br>LOCATION SIGN NOT VISIBLE |                                     |  |  |                              |                   |  |  |
|                               | -                 | 200/110/10/1   |                                     |  |  |                              |                   |  |  |

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely ). COArtesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.