

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JAN 31 2017

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

## Release Notification and Corrective Action

*DAB17033310139* OPERATOR ☒ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd. <i>11010910</i>	Contact	Casey Summers
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Goodnight 27 Federal #4H Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-39142

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	23S	29E					Eddy County, NM

Latitude N 32.26961° Longitude W 103.97466°

## NATURE OF RELEASE

Type of Release	Oil	Volume of Release	60 bbls	Volume Recovered	60 bbls
Source of Release	Tank spilled over	Date and Hour of Occurrence	01/25/2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Braucher, Crystal Weaver- NMOCD; Shelly Tucker- NMOCD		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	01/26/2017		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A tank spilled 60 bbls of oil inside a lined containment. A vacuum truck recovered all the fluids.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 45' x 65' inside a lined containment. Remediation will be completed by recovering all the fluids from within the lined containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: *[Signature]*

Printed Name: Casey Summers

Title: NM Environmental Advisor

E-mail Address: Casey\_Summers@oxy.com

Date: *1-27-17* Phone: (575) 513-8289

Approved by Environmental Specialist *[Signature]*

Approval Date: *2/1/17*

Expiration Date: *N/A*

Conditions of Approval:

*FINAL*

Attached ☐

\* Attach Additional Sheets If Necessary

*2RP-4099*