

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary Designate

Matthias Sayer
Deputy Cabinet Secretary

David R. Catanach, Division Director
Oil Conservation Division



Response Required - Deadline Enclosed

*Field Inspection Program
"Preserving the Integrity of Our Environment"*

HOBBS OCD

FEB 16 2017

RECEIVED

16-Feb-17

PRIDE ENERGY COMPANY
P.O. BOX 701602
TULSA OK 74170-1602

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

Z TAYLOR No.002				G-7-12S-38E	30-025-07161-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/15/2017	Routine/Periodic	Mark Whitaker	Yes	No	3/17/2017	iMAW1704636821
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		No well sign (Rule 19.15.16.8). NEED TO INSTALL WELL SIGN. 2ND NOTICE.				

MARIGOLD UNIT No.001				B-7-12S-38E	30-025-32859-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/15/2017	Routine/Periodic	Mark Whitaker	Yes	No	5/21/2017	iMAW1704637305
Violations						
Absent Well Identification Signs (Rule 103)						
Tank Battery Equipment (Rules 114, 115)						
Comments on Inspection:		No well sign (Rule 19.15.16.8). Fuses down on power pole. Fence down around battery. Heater treater laying on side. NEED TO RE-INSTALL FENCING AROUND BATTERY AND REMOVE SURPLUS EQUIPMENT FROM BATTERY SITE. NEED TO INSTALL WELL SIGN. 1ST NOTICE.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely, *Mark Whitaker, P.E.S.*

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER

FIRST-CLASS MAIL

\$000.46⁰

02/16/2017 ZIP 88240
012E14642224

US POSTAGE

PRIDE ENERGY COMPANY
PO BOX 701602
TULSA, OK 74170-1602