Submit 1 Copy To Appropriate District State of New Mexico	Form C-103			
Office <u>District I</u> – (575) 393-616 1625 N. French Dr., Hobby, WI 882 BTESIA DISTRICT	Revised July 18, 2013			
1625 N. French Dr., Hobbs, TMI 88240 District II – (575) 748-1283 ARTESIA DISTRICT	WELL API NO.			
District II $-(575)$ 748-1283 OIL CONSERVATION DIVISION	30-015-43846			
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 JAN 2 3 2017 CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease			
1000 Rio Brazo Rd Azter NM 87410	STATE FEE			
$\frac{\text{District IV} - (505) 476-3460}{1220 \text{ S. st. Francis Dr., Santa Fe, NM RECEIVED}}$ Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
87505				
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Journey 12 W0MP Fee Com			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number 3H			
1. Type of Well: Oil Well Gas Well Other				
2. Name of Operator	9. OGRID Number 14744			
Mewbourne Oil Company				
3. Address of Operator	10. Pool name or Wildcat			
PO Box 5270, Hobbs NM 88241	Pierce Crossing; Wolfcamp, NW (GAS)			
4. Well Location				
Unit Letter M: 250 feet from the South line and 200	feet from the West line			
Section 12 Township 24S Range 28E 11. Elevation (Show whether DR, RKB, RT, GR, etc.				
11. Elevation (Snow whether DR, RKB, R1, GR, etc.) 2975' GL				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				
TEMPORARILY ABANDON CHANGE PLANS				
PULL OR ALTER CASING				
OTHER: DTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, an				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
01/07/2017 TD 8 ¾" hole @ 9872'. Ran 9862' of 7" 26# P110 LT&C csg. Cmt w/650 sks Lite Class H (50:50:10) w/additives. Mixed @ 11.9#/g w/2.47 yd. Tail w/400 sks Class H w/additives. Mixed @ 15.6#/g w/1.18 yd. Plug down @ 10:30 P.M. 01/07/17. Did not				
bump plug. Cmt pump broke down w/30 bbls left to displace. Cir 11 sks of cmt to the pit. Lift pressure 1000# @ 3 BPM. Tested BOPE to				
5000# & Annular to 3500#. Tested standpipe & mud lines to the pumps to 5000#.Pack-off tested to 5000#. Set mandrel hanger thru				
BOPE w/240k#. FIT test to 13.3 PPG EMW. At 4:30 P.M. 01/09/17, tested csg to 4500# fo				
bit.	,			
Spud Date: 12/22/16 Rig Release Date:				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
Type or print name _Ruby Caballero E-mail address: _rojeda@mewbourne.com PHONE: _575-393-5905 For State Use Only				

APPROVED BY: Anno Approval (if any):	14	TITLE Staff Mar	DATE 3.6.17
Conditions of Approval (if any):	Ţ	- Jong	