NM OF CONSERVATION

MINI OIL CONSERVATION	
30Submit One Copy To Appropriate ARTESIA SUSTRIC State of New Mexico	Form C-103
District I Fig. Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-015-22000
811 S. First St., Artesia, NM 88210 SERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE X FEE
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Empire South Deep Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well x Gas Well Other	8. Well Number 013
2. Name of Operator	9. OGRID Number
Matador Production Company	228937
3. Address of Operator 5400 LBJ Freeway Suite 1500, Dailas TX 75240	10. Pool name or Wildcat South empire Morrow
4. Well Location	
Section 30 Township 17S Range 29E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3646' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON XX REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB 📙
OTHER: Location is ready for OCD inspection after P&A	
X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
_	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
Alchors, dead field, the downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, produ	action equipment and junk have been removed
from lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed.	oved. (Poured onsite concrete bases do not
have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	Times have been removed from lease and wen
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE TITLE Engineer	DATE <u>2/13/17</u>
TYPE OR PRINT NAME Chris Villarreal E-MAIL: cvillarreal@matadorresources.com	PHONE: 972-371-5471
DENIED PAD MEEDS TO BE RE	MOVED OK SPHEAD OUT
APPROVED BY:	PHONE: 972-371-5471 MOVED OR SPREAD OUT OHORS BUHERE REMOVED DATE AUT. Pack how to CURE
MEET AN AF CROFAN	AUT. Packhait CIXZ