Form 3160-5 (June 2015)

(Instructions on page 2)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

# 5. Lease Serial No. NMNM0503

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	1
bandoned well. Use form 3160-3 (APD) for such proposals	5

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.							
					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					greement, Name and/or N	vo.	
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. COTTON DRAW UNIT 158H		
Name of Operator Contact: LINDA GOOD     DEVON ENERGY PROD CO., L.P. E-Mail: linda.good@dvn.com					9. API Well No. 30-015-39729		
3a. Address 333 WEST SHERIDAN AVE. OKLAHOMA CITY, OK 7310	1	Field and Pool or Exploratory Area     COTTON DRAW					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 11 T25S R31E Mer NMP SESE 330FSL 66FEL					EDDY COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES) TO INI	DICATE NATURE OI	F NOTICE, R	EPORT, OR O	THER DATA		
TYPE OF SUBMISSION		ACTION					
☑ Notice of Intent	☐ Acidize ☐	Deepen	☐ Production	n (Start/Resume)	■ Water Shut-O	)ff	
_	☐ Alter Casing 〔	☐ Alter Casing ☐ Hydraulic Fracturing ☐ Reclaim		on	■ Well Integrity	/	
☐ Subsequent Report	<del>-</del>	New Construction	☐ Recomple		Other		
☐ Final Abandonment Notice		Plug and Abandon	▼ Temporari	-			
13. Describe Proposed or Completed Op	<u> </u>	] Plug Back	☐ Water Dis	<u> </u>			
testing has been completed. Final Aldetermined that the site is ready for the Devon Energy Production Co. This well is uneconomic due to production when capacity is a	., L.P. respectfully requests approof of disposal capacity, but will be evaluable.  Le w/ out approved	oval to shut-in this well requirements, including the shut-in this well really and regularly and response SEE	ing reclamation, I for 1 year. returned to	HED FOF	ed and the operator has  SIL CONSERV.  ARTESIA DISTRIC  APR 1 0 2017  RECEIVED:  PROVAL	MisO T	
14. I hereby certify that the foregoing is		NMOCU 1	4/15/17		<del>/</del>		
Name(Printed/Typed) LINDA GO	For DEVON ENERGY PF Committed to AFMSS for processi	ROD CO., L.P., sent to to ing by DEBORAH MCKI	he Carisbað	3/2017 ()			
Traine (17 micas 13 pea) ENVDA OC	JOD	THE REGUL	100	<b>WPPRO</b>	<del>\f\) / /</del>		
Signature (Electronic	Submission)	Date 02/21/20	017	ALTIO			
	THIS SPACE FOR FED	ERAL OR STATE	OFFICE USE	MAR 28	2017/ \/h		
Approved By		Title		mil	W W W		
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condi	ant or		CARLSBAD FILE	OFFICE			
Title 18 U.S.C. Section 1001 and Title 43			willfullyto make	to any department	t or agency of the United		
	statements or representations as to any ma		1/	1	11		

## **BUREAU OF LAND MANAGEMENT Carlsbad Field Office** 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

## Approved for a period of 12 months ending 03/28/2017 subject to conditions of approval.

### Temporary Abandonment of Wells on Federal Lands **Conditions of Approval**

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing intégrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

### **Cotton Draw Unit 158H**

- 1. Well is approved to be TA/SI for a period of 12 months or until 03/28/2018
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 03/28/2018
- 4. COA's met at this time.