State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen

Cabinet Secretary

Matthias Sayer

Deputy Cabinet Secretary

David CatanachDivision Director





Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

28-Jun-17

TANDEM ENERGY CORPORATION

2700 Post Oak Blvd Suite 1000 Houston TX 77056-7056

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTIO	N DETAIL	L SECTION		
VOLA FEDERAL Inspection		No.002		L-1-17S-31E *Significant	30-015-23835-00-00 Corrective	
Date	Type Inspection	Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
06/28/2017	Routine/Periodic	Tony Morales	Yes	No	10/1/2017	iTM1717950259
	Violations					
	General Housekeeping (Rul	e 114)				
Comments	on Inspection: OK. All 19.15.35	Equipment and Location in 5.7B	Goo Shape.	PJ. STAINING ARC	OUND WELL HEAD.	
ARCO FEDERAL No.001				O-1-17S-31E 30-015-23927-00-00		00
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/28/2017	Routine/Periodic	Tony Morales	Yes	No	10/1/2017	iTM1717948668
	Violations					
	General Housekeeping (Rul	e 114)				
Comments	on Inspection: OK. All	Equipment and Location in	Good Shape	. PJ. TANK BATTI	ERIES NO PLACARI	OS /

WINDSOCK OLD TANK BATTERIES ON LOCATION 19.15.35.7B

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.