Submit One Copy To Appropriate District Office	State of New Mex	xico	Form C-103
District I	Energy, Minerals and Natural Resources		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II 811 S. First St., Artesia, NM 88210			30-015-33289 5. Indicate Type of Lease
District III	1220 South St. Francis Dr.		STATE STATE FEE
District IV	io Brazos Rd., Aziec, NM 87410 Sonto Eo. NIM 97505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	·		B-8096
87505	EC AND DEPONTS ON WELLS		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name TDC 8 STATE
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			8. Well Number
PROPOSALS.) 1. Type of Well: Gas Well Other			8 & A
2. Name of Operator			9. OGRID Number
OXY USA INC		16696	
3. Address of Operator			10. Pool name or Wildcat
PO BOX 4294; HOUSTON, TX 77210		MILLMAN YATES SRQNGBSA, EAST	
4. Well Location			
1	from the NORTH line and 660 fe	et from the WEST	lina
			ittic
Section 8 Township 19		County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3378'			
12. Check Appropriate Box to			oata .
12. Check Appropriate Box to 1	midicate ivature of ivotice, Ki	cport of Other D	rata
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOL			
TEMPORARILY ABANDON		ILLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	T JOB 🔲
07.155			
OTHER:			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
El Troise manage de la constitución de la constituc			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
✓ The leastion has been leveled as			have alread of all leads work flow lines and
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
	emaining well on lease; all electri	cal service poles an	nd lines have been removed from lease and well
location, except for utility's distribution	_		location as an active SWA
	facility.		
When all work has been completed, re	eturn this form to the appropriate I	District office to sch	hedule an inspection.
1-11	Cel		
SIGNATURE Warles	TITLE	ENVIRONMENTA	AL ADVISOR DATE 627-17
Alexandra and Carrier and			
TYPE OR PRINT NAME _Wade Dit			
For State Use Only	trich E-MAIL: _wade_dittric	h@oxy.com _ PF	HONE: _575-390-2828
TOT GRACE CIRCLE	0		_
innoverse only	0		_
APPROVED BY: Mart 1. Conditions of Approval (if any):	0		OFFICER DATE 6/29/2017