

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 14 2017

Form C-141
Revised April 3, 2017

RECEIVED Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1725735960 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company: Marathon Oil Company 372098	Contact: Jennifer Van Curen
Address: 5555 San Felipe St., Houston, TX 77056	Telephone No.: 713-296-2500
Facility Name: Red Light 27 34 State Com 2H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No.: 30-015-43917
----------------------	----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	27	23S	26E	150	FNL	990	FWL	Eddy

Latitude 32.28208193 Longitude -104.28644227 NAD83

NATURE OF RELEASE

Type of Release: Produced water / fire	Volume of Release: 0.03 bbls	Volume Recovered: 0 bbls
Source of Release: flare	Date and Hour of Occurrence: 9/13/2017: 1600 hrs	Date and Hour of Discovery: 9/13/2017: 1600 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M Bratcher (OCD) and Amber Groves (SLO)	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Crew was working on site when the dump valve stuck causing fluid (.03 bbls or 1.26 gallons) to go out flare. Fluid caught fire from flare and caught three snake brush on fire. Crew extinguished the flames immediately. Dump valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected by fire was a 10' X 15' area. No clean up action should be needed. Photos attached of burnt snake brush and area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Van Curen</i>		OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen		Approved by Environmental Specialist <i>[Signature]</i>	
Title: Sr. Regulatory Compliance Rep		Approval Date: <u>9/14/17</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>jvancuren@marathonoil.com</u>		Conditions of Approval: <u>FINAL</u>	
Date: 9/14/2017 Phone: 713-296-2500		Attached <input type="checkbox"/> <u>2RP-4387</u>	

* Attach Additional Sheets If Necessary