

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.5. Lease Serial No.
NMLC029342D

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
SEELY OIL COMPANYContact: SHELLIE DAVIS
E-Mail: sdavis@seelyoil.com3a. Address
815 WEST 10TH STREET
FT WORTH, TX 761023b. Phone No. (include area code)
Ph: 817-332-1377
Fx: 817-332-1426

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 9 T17S R30E SWNE 1980FNL 1980FEL

8. Well Name and No.
ARCO FEDERAL 39. API Well No.
30-015-21221-00-S110. Field and Pool or Exploratory Area
SQUARE LAKE

11. County or Parish, State

EDDY COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Final Abandonment Notice
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

08/02/17 MIRU pump. Circulated hole w/ H2O. Gravity Squeeze 50 sx class C cmt @ 2725 & displaced to 3448'. 08/03/17 Gravity Squeeze 25 sx class C cmt w/ 2% CACL @ 1140 & displaced to 1502'. 08/04/17 4 1/2" packer set @ 120'. Gravity Squeeze 100 sx class C cmt w/ 2% CACL & displaced to 400'. 08/07/17 Jim Amos w/ BLM ordered to re-spot plug. Re-squeezed 50 sx cmt w/ 2% CACL @ 120' & displaced to 400'. WOC. Tagged plug @ 503'. Set packer @ 30'. Pressure tested 4 1/2" csg, held 500 psi. Perf'd csg @ 500'. Pressured up on perfs to 800 psi. 08/08/17 Cut off well head. RIH to 503'. Spotted 35 sx class C cmt @ 503' & circulated to surface. RIH w/ 1" hose to 100" in 4 1/2 - 8 5/8" annulus. Spotted 25 sx class C cmt @ 100' & circulated to surface per orders of Jim Amos w/ BLM. Rigged down and moved off. Moved in backhoe and welder. Dug out cellar. Welded on "Underground Dry Hole Marker" Backfilled cellar. Cut off deadmen. Cleaned location, moved off.

ISC 10-30-17
Accepted for record - NMOCD

NM OIL CONSERVATION
ARTESIA DISTRICT
OCT 30 2017
RECEIVED
RECLAMATION
DUE 2-8-18

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #391541 verified by the BLM Well Information System
For SEELY OIL COMPANY, sent to the Carlsbad
Committed to AFMSS for processing by JAMES AMOS on 10/18/2017 (18JA0030SE)

Name (Printed/Typed) DAVID HENDERSON

Title PRESIDENT

Signature (Electronic Submission)

Date 10/11/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By



Title

Supv. AET

Date

10-23-17

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Revisions to Operator-Submitted EC Data for Sundry Notice #391541

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	FAN FAN	FAN FAN
Lease:	NMLC029342D	NMLC029342D
Agreement:		
Operator:	SEELY OIL COMPANY 815 W. 10TH STREET FORT WORTH, TX 76102 Ph: 817-332-1377	SEELY OIL COMPANY 815 WEST 10TH STREET FT WORTH, TX 76102 Ph: 817.332.1377
Admin Contact:	SHELLIE DAVIS PRODUCTION ANALYST E-Mail: sdavis@seelyoil.com Cell: 817-332-1377 Ph: 817-332-1377 Fx: 817-332-1426	SHELLIE DAVIS PRODUCTION ANALYST E-Mail: sdavis@seelyoil.com Cell: 817-332-1377 Ph: 817-332-1377 Fx: 817-332-1426
Tech Contact:	DAVID HENDERSON PRESIDENT E-Mail: dhenderson@seelyoil.com Ph: 817-332-1377 Fx: 817-332-1426	DAVID HENDERSON PRESIDENT E-Mail: dhenderson@seelyoil.com Ph: 817-332-1377 Fx: 817-332-1426
Location:		
State:	NM	NM
County:	EDDY COUNTY	EDDY
Field/Pool:	SQUARE LAKE GRAYBURG - SA	SQUARE LAKE
Well/Facility:	ARCO FEDERAL 3 Sec 9 T17S R30E 1980FNL 1980FEL	ARCO FEDERAL 3 Sec 9 T17S R30E SWNE 1980FNL 1980FEL