

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-28223

Release Notification and Corrective Action

1CLB0523553184

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Merit Energy Company	Contact: Mike Self
Address: P.O. Box 69, Loco Hills N.M., 88255	Telephone No.: 505-677-2327
Facility Name: Keel B # 60	Facility Type: Oil producer

Surface Owner: BLM	Mineral Owner: BLM	Lease No.: LC-029435-B
--------------------	--------------------	------------------------

LOCATION OF RELEASE

Unit Letter C	Section 6	Township 17S	Range 31E	Feet from the 1300	North/South Line North	Feet from the 2450	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.866738 Longitude 103.909526

NATURE OF RELEASE

Type of Release: Crude oil w/ produced water	Volume of Release: <5 bbls	Volume Recovered: 0
Source of Release: Poly flow line	Date and Hour of Occurrence: 07/09/05 AM	Date and Hour of Discovery: 07/09/05 10:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Poly flow line failure. Area affected by overspray treated with Micro-blaze.

Describe Area Affected and Cleanup Action Taken.*

The affected area was approximately 30' X 50'. The affected area was treated with M-1000 (a microbial hydrocarbon degrader) and roto-tilled on 3/28/06 to blend and aeriate the soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Mike Self	Approved by District Supervisor:	TIM GUM by MB 
Title: Area Foreman	Approval Date: 4/13/06	Expiration Date:
E-mail Address: m.self@meritenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-10-06	Phone: 505-677-2327	

* Attach Additional Sheets If Necessary