District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notificat	ion and (Corrective A	ction		^	
NAB1810358199	OPE	RATOR	X Initi	al Report	Final Report	
Name of Company Vanguard Operating, LLC 258350						
Address 5847 San Felipe, STE 3000 Houston, TX 77057		Telephone No.505-918-0523				
Facility Name AID 24 State #8Battery	Facility 7	ype Tank Battery				
Surface Owner Mineral Own	er State	***************************************	API No	3001537557		
LOCATI	ON OF R	ELEASE				
Unit Letter Section Township Range Feet from the No. 24 17S 28E 2310	orth/South Lin South					
Latitude 32.82014	Longitude	-104.126812 NAI	083	•		
				F		
Type of Release Gas/Emissions	Volume	Volume of Release 250 MCFD Volume Recovered 0				
Source of Release Flare		d Hour of Occurrence	e Date and	Date and Hour of Discovery N/A		
Was Immediate Notice Given?		2-3-2018 If YES, To Whom?				
X Yes No Not Require		Amalia Bustamante by email				
By Whom? Chuck Johnston		Date and Hour 7:30 pm 2-3-2018				
Was a Watercourse Reached?		If YES, Volume Impacting the Watercourse.				
☐ Yes X No						
If a Watercourse was Impacted, Describe Fully.*						
N/A						
N/A						
Describe Cause of Problem and Remedial Action Taken.*						
Purchaser found leak on their pipeline and requested a volume reducti	on while mak	no renairs Gas was	sent to flare for tu	vo dave		
r dichasel found leak on their piperine and requested a volume reducti	on wille mak	ing repairs. Gas was	Schi to haic for tv	vo days.		
Describe Area Affected and Cleanup Action Taken.*						
No impact.						
I hereby certify that the information given above is true and complete	to the hest of	my knowledge and y	nderstand that nur	cuent to NMOCD	rules and	
regulations all operators are required to report and/or file certain relea						
public health or the environment. The acceptance of a C-141 report b	y the NMOCI	marked as "Final R	eport" does not rel	ieve the operator of	of liability	
should their operations have failed to adequately investigate and reme or the environment. In addition, NMOCD acceptance of a C-141 repo						
federal, state, or local laws and/or regulations.	ort does not re	ieve the operator of	responsibility for t	compliance with air	ny otner	
001/1/		OIL CON	SERVATION	DIVISION		
(M) 1 X					for reco	
Signature:	┦		N	1 - 0	Ca vell	
Printed Name: Chuck Johnston	Approved	Approved by Environmental Specialist:				
Title: EHS Specialist	Approval	Approval Date: 4 12 18 Expiration Date: N/A				
		110010	1			
E-mail Address: cjohnston@vnrenergy.com	Condition	s of Approval:		Attached	1. 01	
Date: 2-9-2018 Phone: 432-202-4771		Max		JARP.	4646	
Attach Additional Sheets If Necessary			***************************************	-14		
112/18 AB						