Submit One Copy To Appropriate District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Resources WELL API NO. 30-015-29871 5. Indicate Type of Lease STATE FEE X
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SU PROPOSALS.) 1. Type of Well: \(\times \) Oil Well \(\times \) Gas Well \(\times \) Other	The state of the s
2. Name of Operator Cimarex Energy Co. of Colorado	9. OGRID Number 162683
3. Address of Operator 202 S. Cheyenne Ave., Suite 1000, Midland TX 79705	10. Pool name or Wildcat Happy Valley; Morrow
4. Well Location Unit Letter N : 281 feet from the S line and 1924 feet from the W line Section 13 Township 22S Range 25E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3404' 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB	
OTHER:	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Amithy Crawford TITLE Reg	ulatory AnalystDATE4/5/2018
TYPE OR PRINT NAME Amithy Crawford E-MAIL: ac	rawford@cimarex.com PHONE: 432-620-1909
APPROVED BY:TITLE	DENIED DATE 4-12-18