| Submit 1 Copy To Appropriate District State of New Office | |
|---|--|
| District 1 – (575) 393-6161 Energy, Minerals and 1 1625 N. French Dr., Hobbs, NM 88240 | WELL API NO. |
| District II - (575) 748-1283 | ON DIVISION 30-015-43807 |
| 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. | 1 3 Indicate Type of Lease |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 Santa Fe, NI | SIAID IDD E |
| 1220 S. St. Francis Dr., Santa Fe, NM | |
| SUNDRY NOTICES AND REPORTS ON WI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN C | R PLUG BACK TO A |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1 PROPOSALS.) | Black River SWD |
| 1. Type of Well: Oil Well Gas Well & Other SWD | 8. Well Number 1 |
| 2. Name of Operator MATADOR PRODUCTION COMPANY | 9. OGRID Number 228937 |
| 3. Address of Operator | 10. Pool name or Wildcat |
| 5400 LBJ FREEWAY, STE 1500, DALLAS | , TX 75240 SWD;DEVONIAN |
| 4. Well Location Unit Letter C : 250 feet from the | N line and 2461 feet from the W line |
| Unit Letter C : 250 feet from the Section 31 Township 23S | Range 28E NMPM County |
| 11. Elevation (Show whether | 3 |
| 312 | 6' GR |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | |
| NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON | |
| TEMPORARILY ABANDON | |
| PULL OR ALTER CASING MULTIPLE COMPL | CASING/CEMENT JOB |
| DOWNHOLE COMMINGLE | 1 |
| CLOSED-LOOP SYSTEM OTHER: | OTHER: Upgrade tubing |
| 12 Describe proposed or completed operations (Clearly sta | te all pertinent details, and give pertinent dates, including estimated date |
| of starting any proposed work). SEE RULE 19.15.7.14 | NMAC. For Multiple Completions: Attach wellbore diagram of |
| proposed completion or recompletion. | N - OH - Description |
| 03/06/18 - 03/15/18 Remove existing 4.5" fiberglass tubing and replace with 5.0" plastic-coated tubing. | |
| Weatherford AS1-X packer set @ 13,163 ' with tubing hanger. Installed 5.0" plastic-coated tubing. | |
| Pressure -tested well to 850 psi for 30 minutes, dropped 70 psi during test. | |
| NMOCD inspector Richard Inge witnessed successful MIT test. | |
| Resumed injection. | NM OIL CONSERVATION ARTESIA DISTRICT |
| PER R-14 | |
| 762 K-19 | 427 APR 18 2018 |
| | , |
| (Order SWD -1627) | RECEIVED |
| Pig Pel | ease Date: 10/29/2016 |
| Spud Date: 08/21/2016 Rig Rel | asc Date. |
| | |
| I hereby certify that the information above is true and complete t | o the best of my knowledge and belief. |
| 0-0 | 11/1/10 |
| CIONATURE TITLE | Area Production Manager DATE 9/17 18 |
| JRon | ano@matadorresources.com |
| Type or print name John Romano E-mail address: PHONE:972-371-5245 | |
| For State Use Only | |
| | 1 1 - |
| APPROVED BY: RILLARD NGE TITLE | Compliques OFFICER DATE 4/25/18 |