

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 23 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
DISTRICT II-ARTESIA O.C.D. accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB181435284 **OPERATOR** ☒ Initial Report ☒ Final Report

Name of Company Marathon Oil Permian LLC 372098	Contact Callie Karrigan
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)
Facility Name: Southern Comfort 25 36 State X No. 001H	Facility Type Oil and gas production facilities

Surface: Owner: state	Mineral: Owner: state	API No. : 30-015-44332
-----------------------	-----------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	25	24S	28E	2490	South	2310	East	Eddy

Latitude 321882. Longitude -104.0400

NATURE OF RELEASE

Type of Release: Fire	Volume of Release: 0	Volume Recovered: 0
Source of Release: enardo valve	Date and Hour of Occurrence 05/22/2018 1:00 am	Date and Hour of Discovery 05/22/2018 1:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – Eddy County, Ryan Mann	
By Whom? Callie Karrigan	Date and Hour 05/22/2018 5:23 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* Not applicable.		
Describe Cause of Problem and Remedial Action Taken.* A water hauler reported that the Southern Comfort battery had been struck by lightning. The Production Supervisor arrived on location and observed that two enardo valves at each end of the tank battery were on fire. The Supervisor immediately shut both wells and dispatched the fire department; however, the fires self-extinguished before the fire department arrived.		
Describe Area Affected and Cleanup Action Taken.* The wells were shut-in pending enardo replacement and thorough investigation of the facility prior to bringing the wells back online. There was no release of fluids or impact to the ground or containment.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Callie Karrigan Signature:	OIL CONSERVATION DIVISION	
Printed Name: Callie Karrigan	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: HES Environmental Professional	Approval Date: 5/23/18	Expiration Date: N/A
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval:	
Date: 5/23/2018 Phone: 405-202-1028(cell) 575-297-0956 (office)	FINAL	Attached <input checked="" type="checkbox"/> 2P-4770

* Attach Additional Sheets If Necessary