## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen

Cabinet Secretary

**Matthias Sayer** 

**Deputy Cabinet Secretary** 

Heather Riley
Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

21-May-18

## **COG OPERATING LLC**

05/21/2018 Routine/Periodic

One Concho Center 600 W. Illinois Ave Midland TX 79701-9701

**LETTER OF VIOLATION - Inspection** 

iTM1814134951

8/24/2018

## Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTIO	N DETAIL	SECTION		
DODD FED Inspection Date	ERAL UNIT N		Violation?	H-22-17S-29E *Significant Non-Compliance?	30-015-30153-00-00 Corrective Action Due By:	Inspection No.
05/21/2018	Routine/Perio	dic Tony Morales	Yes	No	8/24/2018 i	TM1814133276
Comments	on Inspection:	OK. All Equipment and Location in 19.15.29	n Good Shape	. PJ STAINING AF	ROUND WELLHEAD	
DODD FED	ERAL UNIT	No.670		I-15-17S-29E	30-015-41302-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.

Yes

No.

Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ STAINED AREA SOUTEAST OF PJ

APPROX 10' X 20' 19.15.29

**Tony Morales** 

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.