District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

MAY 3 1 2018

Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in DISTRICT II-ARTES With 19.15.29 NMAC.

Release Notificatio	and Correctiv	e Action
---------------------	---------------	----------

_nable	81575	57897				OPERA?	ГOR			al Report	$\boxtimes$	Final Report
Name of Company Devon Energy Production Company [1]3					013 10	Contact Merle Lewis, Production Foreman						
		Rivers Hwy			-	Telephone No. 575-748-3371						
Facility Name Tomb Raider 1 Fed 1H Battery F						Facility Type Battery						
Surface Owner Federal Mineral Owner F						ederal			API No	. 30-015-42	<del></del> 2655	
LOCATION OF RELEASE												
Unit Letter   Section   Township   Range   Feet from the   Nort						South Line	Feet from the	East/\	t/West Line   County			
В	1	23S	31E	200'	FNL		2005'	FEL		Eddy		
Latitude_32.3400421_ Longitude_103.7294922_ NAD83												
NATURE OF RELEASE												
Type of Release						Volume of Release Volume Recovered						
Natural Gas Source of Release						657.4 MCI	F Iour of Occurrenc		0 MCF	II CD:		
Three-Phase							018 @ 7:33 AM	æ		Hour of Dise 2018 @ 7:33		
Was Immedia						If YES, To	Whom?		<u> </u>			
		$\boxtimes$	Yes _	No Not Re	equired	Mike Bratcher, OCD						
					Crystal Weaver, OCD Shelly Tucker, BLM							
By Whom?						Date and Hour						
Brett Fulks, EHS Professional						May 18, 2018 @ 7:17 AM						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. N/A						
If a Watercourse was Impacted, Describe Fully.*												
N/A												
Describe Cause of Problem and Remedial Action Taken.*  Back pressure valve on the three-phase separator failed causing the PRV to open. The well was shut in to stop the release and repairs have been made.												
Dack pressure	e vaive on t	ne unee-pnas	е ѕерагаю	r raned causing in	e PKV IC	open. The	well was shut in t	o stop t	ne reiease a	ina repairs n	ave bee	en made.
Describe Are	a Affected	and Cleanup A	Action Tal	en.*								-
Approximate												
												•
I hereby certi	fy that the i	information gi	ven above	is true and comp	lete to the	e best of my	knowledge and u	ndersta	nd that nurs	suant to NM	OCD n	iles and
regulations al	ll operators	are required to	o report ar	nd/or file certain re	elease no	tifications a	nd perform correc	tive act	ions for rele	eases which	may en	ndanger
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,						es not renev		Capona	ionity for c	omphance w	Till ally	Ottlei
						OIL CONSERVATION DIVISION						
Signature: Sheila Fisher						<i>A</i> ,						
						Approved by Environingental Specialist & Examina						
Printed Name: Sheila Fisher												
Title: Field A	Admin Sunn	oort				Approval Dat	e 10/5/18	•	Expiration 1	Date: A/	ĪĀ	
				-					Expiration !	Date. /4/	. , ,	
E-mail Address: Sheila.Fisher@dvn.com  Conditions of Approval:  Attached									1.00			
Date: 5/18/18 Phone: 575.748.1829 FINAL Attached 20 473										- <i>47X</i> ()		

<sup>\*</sup> Attach Additional Sheets If Necessary