RECEIVED	is form for proposals to	NTERIOR GEMENT RESENTATIONS OF FILE drill or to re-enter as a	OMB Expires Id Office Scrial No. Scrial No. 1435 6. If Indian, Allotte	e or Tribe Name reement, Name and/or No.
Oil Well Gas Well Oth 2. Name of Operator	9. API Well No.			
STRATA PRODUCTION COM	30-015-21126	6-00-S1		
3a. Address ROSWELL, NM 88202-1030		3b. Phone No. (include area code) Ph: 575-622-1127 Ext: 20 Fx: 575-623-3533	10. Field and Pool FORTY NINE	or Exploratory Area R RIDGE
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description		11. County or Paris	h, State
Sec 24 T23S R30E SWNW 1979FNL 660FWL			EDDY COUN	TY, NM
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR O	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent □ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete	Water Shut-Off Well Integrity Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	▼ Temporarily Abandon	
	Convert to Injection	☐ Plug Back	☐ Water Disposal	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.				
"NON COMPLIANT" BY MR. REPORTS AND DAILY REPORTS	SWARTZ. SEVERAL CO DRTS FROM OLD RECO	7 WHICH WAS "ACCEPTED F INVERSATIONS AND MORE RDS WERE SUPPLIED TO M IGE PLUG WERE COMPETEI	INFORMATION INCLUDING R. SWARTZ WHO AGREED	DRILLING THAT THE PLUGS
ON AUGUST 1, 2017 NMOCD REQUESTED THE SANDY #1 EITHER BE RETURNED TO PRODUCTION OR TEMPORARILY ABANDONES SINCE THE WELL HAS NOT PRODUCED IN SEVERAL MONTHS AND IS CURRENTLY CLASSIFIED AS AN				
WELL BORE DIAGRAM IS A	TTACHED AND ALL PRO D TO 500 PSIG FOR 30 M	S THAT THE WELL BE CLASS DDUCING PERFS HAVE BEE MINUTES, HOWEVER, STRA	N SQUEEZED. THE CASING TA IS WILLING TO REPEAT	G AND SQUEEZE THE
			Accepted to	or record

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #384416 verified by the BLM Well Information System

For STRATA PRODUCTION COMPANY, sent to the Carlsbad

Committed to AFMSS for processing by PRISCILLA PEREZ on 09/20/2017 (17PP0912SE) Title **OPERATIONS MANAGER** Name (Printed/Typed) PAUL RAGSDALE Signature (Electronic Submission) 08/11/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

_Approved By	/s/ Jonathon Shepard
	, if any, are attached. Approval of this notice does not warrant on the holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #384416 that would not fit on the amsbad Field Office

32. Additional remarks, continued

OCD Artesia

STRATA IS REQUESTING TA STATUS FOR THIS WELL FOR AT LEAST 1 YEAR OR UNTIL COMMODITY PRICES IMPROVE
TO ECONOMICALLY JUSTIFY THE RE-ENTRY AND DRILLING OF A HORIZONTAL LATERAL IN THE LOWER BRUSHY
CANYON FORMATION.

Carlsbad Field Office Well: SANDXFEDERAL I **Operator: Strata Production Company** BHL: NM114356 Surface Lease: NM114356 @ Srfce: T23S-R30E,24.1979n660w **Lease Agreement** Case No: NM114356 @ M TD: T23S-R30E,24.1979n660w **Subsurface Concerns for Casing Designs:** KB: 3290 Estate: F\F\F Well Status: OSI CWDW, R of W: GL: 3267 Spud date: 3/29/1974 OCD Admn Order, date: Corr: 23 Plug'd Date: Frmtn, Depths, psig: Reentry Date: 1(150 Rustler) 465, 20"hole, 16"65# H40 csg, ST&C, Mix 525sx, circ 162sx 03/31/1974 (470 Salado) 08/24/1992 515 spot 125sx cmt plug, circ 10sx to surface 08/24/1992 1080 spot 25sx cmt plug <1830> saz'd w/375sx,circ25sx to sfc 05/23/1974 1870 TOC Sqz'd from 8050 (2290 Castile) (3868 Delaware Lime) 3900,15"hole,10.75" 51# K55 csg ST&C, Mix 2950sx, circ 580sx 04/12/1974 3950 spot 50 sx cmt plug, tag at 3731 08/24/1992 07/10/2009 <5897-917> sqz'd w/200sx, (unreported perfs to 6101), 08/01/16 07/07/2009 <6453-62> sqz'd w/100sx, (unreported perfs to 6532), 08/08/16 7174 set CICR, sqz perfs w/150sx, 08/15/16 01/09/2006 <7666-94> sqz'd w/100sx, (unreported perfs from 7363), 08/06/16 7700 DV Tool (7738 Bone Springs) 08/24/1992 7750 spot 50sx cmt plug 01/09/2006 7990 CIBP w/cmt cap 05/21/1974 <8050> sqz'd 1666sx thru perfs 8080 top of sqz from 12000' CBL bond per sundry 08/24/1992 (10685 3rd Bone Springs) spot 45sx plug 10685-10585 08/24/1992 (11140 Wolfcamp) spot plg #3 11140-11040 08/24/1992 11596 tag plug w/tbg 11660 TOL 08/21/1992 11710 Spot ?sx Class "H" cmt <12000> unable to circ thru shoe, pmpd 800sx, sqz'd 50sx out csg perfs 05/16/1974 <12056> unable to pump into at 5750psig 3rd Csg in 2nd Csg: 12070,9.5"hole, 7.625" 26.4# L80 BTC csg DV Tool@7700 Experienced cementing difficulties Some of Sundry Report shows 7 7/8" csg, may be misprint (13020 Strawn) (13185 Atoka) (13960 Morrow Lime) 14180 CIBP w/45sx Class "H" cmt 08/20/1992 (14222 Morrow Sand) <14392-412> 09/17/1987 09/08/1987 14480 CIBP w/cmt cap 07/19/1974 <14494-650> (14727 4th Morrow Sand) Diagram last updated: 07/20/2017 06/22/1974 14857, 6.75" hole, 5.5" 20# \$95 Flush Seal-Lock csg, Mix 325sx, circ sx

BUREAU OF LAND MANAGEMENT Carlsbad Field Office Carlsbad Field Office 620 East Greene Street Arisbad Field Office Carlsbad, New Mexico 88220 575-234-5972 Carlsbad Field Office Carlsbad Field Office

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.