

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS****Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.**5. Lease Serial No.
NMNM0557370

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
EAGLE 34 J FEDERAL 819. API Well No.
30-015-4377210. Field and Pool or Exploratory Area
RED LAKE, GL-YO NE 9683611. County or Parish, State
EDDY COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
LIME ROCK RESOURCES II-A, L.P. Contact: MIKE PIPPIN
E-Mail: MIKE@PIPPINLLC.COM3a. Address
C/O MIKE PIPPIN 3104 N. SULLIVAN
FARMINGTON, NM 874013b. Phone No. (include area code)
Ph: 505-327-4573

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 34 T17S R27E NWSE 1790FSL 1650FEL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other
Surface Rehabilitati
on

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

THIS NEW WELL IS READY FOR INTERIM REMEDIATION INSPECTION.

This new well was completed on 1/6/17. The location has been down sized and reseeded and is now ready for inspection.

GC 6-4-18
Accepted for record - NMOC

5/21/18 - 102 is Good to Go. OK to approve (HP)

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #371392 verified by the BLM Well Information System
For LIME ROCK RESOURCES II-A, L.P., sent to the Carlsbad
Committed to AFMSS for processing by DEBORAH MCKINNEY on 03/29/2017 ()

Name (Printed/Typed) MIKE PIPPIN

Title PETROLEUM ENGINEER

Signature (Electronic Submission)

Date 03/28/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****

Updated 2/25/99

**UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

SURFACE INSPECTION FORM

Well Name: EAGLE 34 J FEDERAL			Well #: 81		API #: 300154377200S1		Well Status: POW	
Footage: 1790FSL 1650FEL		Alliquot: NWSE	Lot/Tract:	Section: 34	Twnship/Lat: 17S	Rng/Long: 27E	County: EDDY	State: NM
Case: NMNM0557370		Facility ID:			Associated Rights of Way:			
Lease: NMNM0557370		H2S Date:		H2S Gas Stream:		H2S Vapors:		H2S Radius:
Hazard: No								
SME: BUREAU OF LAND MANAGEMENT			Operator Name: LIME ROCK RESOURCES II A LP					

Please be sure to complete for inspection

Inspector: <i>H. Price</i>		Company/SME Rep:				Phone #:	
Date: <i>5/21/18</i>		Type: <i>ES</i>	Activity: <i>IR</i>	Office: <i>1.2</i>	Travel: <i>1.5</i>	Insp: <i>1.2</i>	

General Remarks:

5/15/18- ES/IR inspection conducted on the above location while in the area. Well identification sign is present, accurate, and legible with all required information. Berms are present around the well pad. Barricades present around all moving parts. Belt guard in place. No housekeeping issues identified. Pumpjack is painted shale green. IR COMPLETED. 100 ft. on the N side. 80 ft. on the E side. and 40 West of the lease/ access road. Approx 1 acre reclaimed. No vegetation present on IR. No contaminants identified. No noxious or invasive weeds identified. No erosions issues identified. No issues found. IR is good to go.

Author: HENRYETTA PRICE

Date: 05/21/2018

1 trip.

Follow-up Requirements: (circle any that apply) NONE VERBAL LETTER INC NOTIFY PET

Follow-up Remarks:

CORRECT PROBLEM BY:

NEXT INSPECTION: