

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 18 2018

Form C-141  
Revised April 3, 2017

DISTRICTS ARTESIA, NM O.C.D. appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

NAB1817255074

## OPERATOR

X Initial Report X Final Report

Name of Company	Vanguard Operating, LLC 258350	Contact	Jason Fisher
Address	5847 San Felipe, Ste. 3000 Houston, TX 77057	Telephone No.	505-918-0523
Facility Name	Staley State Battery Staley State #001 Well	Facility Type	Central Battery and Well Site
Surface Owner	Mineral Owner	State	API No. 30-015-31284

## LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	30	17S	28E	2310	South	1650	East	Eddy

Latitude 32.8041534 Longitude -104.2117538 NAD83

## NATURE OF RELEASE

Type of Release	Gas	Volume of Release	395 mcf	Volume Recovered	0
Source of Release	Flare	Date and Hour of Occurrence	6-12-2018	Date and Hour of Discovery	6-12-2018
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No X Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No				
If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Gas purchaser requested curtailment of gas due to compressor problems on their residue line. The gas was sent to flare for 18 hours.					
Describe Area Affected and Cleanup Action Taken.*					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chuck Johnston	Approved by Environmental Specialist: 	
Title: EHS Specialist	Approval Date: 6/18/18	Expiration Date: N/A
E-mail Address: cjohnston@vnrenergy.com	Conditions of Approval: FINAL	Attached: 2RP-4821
Date: 6-18-2018	Phone: 432-202-4771	

\* Attach Additional Sheets If Necessary