## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer

**Deputy Cabinet Secretary** 

Heather Riley
Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

03-Jul-18

## **BURNETT OIL CO INC**

Burnett Plaza, Suite 1500 801 Cherry St., Unit 9 Fort Worth TX 76102-6102

**LETTER OF VIOLATION - Inspection** 

## Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO	N DETAIL	SECTION	<del></del>			
GRAYBURG JACKSON Inspection Date Type Inspection				Violation?	I-12-17S-30E *Significant Non-Compliance?	30-015-04128-00-0 Corrective Action Due By:	O Inspection No.		
07/03/2018	Routine/Periodic		Tony Morales	Yes	No	10/6/2018	iTM1818447408		
Comments	on Inspection:	OK. All Equipm 19.15.29	ent and Location in	Good Shape.	PJO. STAINING A	ROUND WELL HEA	D		
GISSLER B Inspection Date	No.005  Type Inspection	1	Inspector	Violation?	J-23-17S-30E *Significant Non-Compliance?	30-015-04300-00-0 Corrective Action Due By:	Inspection No.		
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818431903		
Comments	on Inspection:		ent and Location in LHEAD / LOCATI			GN WORN STAININ	G		
GISSLER B Inspection Date	No.012  Type Inspection	1	Inspector	Violation?	I-23-17S-30E *Significant Non-Compliance?	30-015-04302-00-0 Corrective Action Due By:	Inspection No.		
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818432419		
Comments on Inspection:		OK. All Equipment an Location in Good Shape. PJO. STAINING AROUND WELL HEAD. LOCATION SIGN WORN FADED 19.15.29							

JACKSON B No.024 L-24-17S-30E 30-015-04320-00-00 \*Significant Corrective Inspection Type Inspection Violation? Inspection No. Inspector Non-Compliance? Action Due By: Routine/Periodic 07/03/2018 Yes Tony Morales Nο 10/6/2018 iTM1818432803 Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELL HEAD+. STAINED AREA APPROX 60' SOUTH 40' WEST X 5' 19.15.29 **JACKSON B** No.034 E-24-17S-30E 30-015-27440-00-00 \*Significant Inspection Corrective Date Type Inspection Inspector Violation? Non-Compliance? Action Due By: Inspection No. 07/03/2018 Routine/Periodic iTM1818436033 **Tony Morales** Yes No 10/6/2018 **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELL HEAD 19.15.29 **GISSLER B** No.030 G-23-17S-30E 30-015-27922-00-00 Inspection \*Significant Corrective Type Inspection Inspector Violation? Inspection No. Date Non-Compliance? Action Due By: 07/03/2018 iTM1818433619 Routine/Periodic Tony Morales Yes No 10/6/2018 **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD 19.15.29 **STEVENS A No.010** L-13-17S-30E 30-015-32793-00-00 Inspection Significant Corrective Type Inspection Inspector Violation? Inspection No. Date Non-Compliance? Action Due By: iTM1818440905 07/03/2018 Routine/Periodic **Tony Morales** Yes No 10/6/2018 **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD 19.15.29 **STEVENS A No.011** F-13-17S-30E 30-015-33131-00-00 Inspection \*Significant Corrective Inspection No. Type Inspection Inspector Violation? Non-Compliance? Action Due By: Date 07/03/2018 Routine/Periodic **Tony Morales** Yes No 10/6/2018 iTM1818444208 **Comments on Inspection:** OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELLHEAD 19.15.29 N-13-17S-30E 30-015-34225-00-00 STEVENS A No.012 Inspection \*Significant Corrective **Type Inspection** Inspector Violation? Inspection No. Date Non-Compliance? **Action Due By:** iTM1818442078 07/03/2018 Routine/Periodic **Tony Morales** Yes 10/6/2018 No Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD 19.15.29 G-13-17S-30E 30-015-34502-00-00 JACKSON A No.035 \*Significant Corrective Inspection Violation? Inspection No. Type Inspection Inspector Date Non-Compliance? **Action Due By:** 07/03/2018 Routine/Periodic **Tony Morales** Yes 10/6/2018 iTM1818445185 No **Comments on Inspection:** PJ. CONTAMINATED MATERIAL ON OK. All Equipment and Location in Good Shape. LOCATION. STAINING AROUND WELL HEAD. 19.15.29 A-13-17S-30E 30-015-34765-00-00 JACKSON A No.027Q \*Significant Corrective Inspection Violation? Type Inspection Inspector Inspection No. Non-Compliance? Action Due By: Date iTM1818446107 07/03/2018 Routine/Periodic **Tony Morales** Yes No 10/6/2018 Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ WRONG API ON LOCATION SIGNSHOULD BE "34765" NOT 34452 19.15.16.8 D-24-17S-30E 30-015-41176-00-00 **GISSLER B No.095** Inspection \*Significant Corrective Inspector Violation? Inspection No. Type Inspection Date Non-Compliance? Action Due By: Yes iTM1818437378 07/03/2018 Routine/Periodic **Tony Morales** 10/6/2018 Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD 19.15.29

GISSLER A Inspection Date	No.043  Type Inspection	ı	Inspector	Violation?	B-23-17S-30E *Significant Non-Compliance?	30-015-41177-00-0 Corrective Action Due By:	00 Inspection No.		
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818435095		
Comments	on Inspection:	OK. All Equipm 19.15.29	ent and Location in	n Good Shape.	PJO. STAINING A	ROUND WELL HEA	D		
JACKSON Inspection Date 07/03/2018	A No.044  Type Inspection  Routinc/Perio		Inspector Tony Morales	Violation? Yes	P-12-17S-30E *Significant Non-Compliance?	30-015-41539-00-0 Corrective Action Due By: 10/6/2018	00 Inspection No. iTM1818446557		
,,	on Inspection:		•			OUND WELL HEAD.			
GISSLER B Inspection Date	Type Inspection	No.104	Inspector	Violation?	H-23-17S-30E *Significant Non-Compliance?	30-015-41801-00-0 Corrective Action Due By:	OO Inspection No.		
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818434273		
Comments	on Inspection:	OK. All Equipm 19.15.29	ent and Location in	n Good Shape.	PJO STAINING A	ROUND WELLHEAD	)		
JACKSON Inspection Date	B No.070  Type Inspection	ı	Inspector	Violation?	F-24-17S-30E *Significant Non-Compliance?	30-015-42043-00-( Corrective Action Due By:	OO Inspection No.		
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818443221		
Comments on Inspection:		OK. All Equipm 19.15.29	ent and Location in	n Good Shape.	PJO STAINING A	ROUND WELLHEAD	)		
JACKSON Inspection Date	A Type Inspection	No.050	Inspector	Violation?	P-12-17S-30E *Significant Non-Compliance?	30-015-42212-00-0 Corrective Action Due By:	OO Inspection No.		
07/03/2018	Routine/Perio	dic	Tony Morales	Yes	No	10/6/2018	iTM1818446991		
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELL HEAD.							

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

19.15.29

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.