

State of New Mexico

Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley
Division Director



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

03-Jul-18

BURNETT OIL CO INC

Burnett Plaza, Suite 1500 801 Cherry St., Unit 9
Fort Worth TX 76102-6102

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

GRAYBURG JACKSON S A UNIT No.036				I-12-17S-30E	30-015-04128-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818447408
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD 19.15.29				

GISSLER B No.005				J-23-17S-30E	30-015-04300-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818431903
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJ. LOCATION SIGN WORN STAINING AROUND WELLHEAD / LOCATION 19.15.25				

GISSLER B No.012				I-23-17S-30E	30-015-04302-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818432419
Comments on Inspection:		OK. All Equipment an Location in Good Shape. PJO. STAINING AROUND WELL HEAD. LOCATION SIGN WORN FADED 19.15.29				

JACKSON B No.024

L-24-17S-30E 30-015-04320-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818432803
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELL HEAD+. STAINED AREA APPROX 60' SOUTH 40' WEST X 5' 19.15.29						

JACKSON B**No.034**

E-24-17S-30E 30-015-27440-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818436033
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELL HEAD 19.15.29						

GISSLER B**No.030**

G-23-17S-30E 30-015-27922-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818433619
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD 19.15.29						

STEVENS A No.010

L-13-17S-30E 30-015-32793-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818440905
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELL HEAD 19.15.29						

STEVENS A No.011

F-13-17S-30E 30-015-33131-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818444208
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELLHEAD 19.15.29						

STEVENS A**No.012**

N-13-17S-30E 30-015-34225-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818442078
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD 19.15.29						

JACKSON A No.035

G-13-17S-30E 30-015-34502-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818445185
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ. CONTAMINATED MATERIAL ON LOCATION. STAINING AROUND WELL HEAD. 19.15.29						

JACKSON A No.027Q

A-13-17S-30E 30-015-34765-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818446107
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ WRONG API ON LOCATION SIGNSHOULD BE "34765" NOT 34452 19.15.16.8						

GISSLER B No.095

D-24-17S-30E 30-015-41176-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818437378
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD 19.15.29						

GISSLER A No.043

B-23-17S-30E

30-015-41177-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818435095
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO. STAINING AROUND WELL HEAD 19.15.29						

JACKSON A No.044

P-12-17S-30E

30-015-41539-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818446557
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELL HEAD. 19.15.29						

GISSLER B No.104

H-23-17S-30E

30-015-41801-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818434273
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD 19.15.29						

JACKSON B No.070

F-24-17S-30E

30-015-42043-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818443221
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELLHEAD 19.15.29						

JACKSON A No.050

P-12-17S-30E

30-015-42212-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2018	Routine/Periodic	Tony Morales	Yes	No	10/6/2018	iTM1818446991
Comments on Inspection: OK. All Equipment and Location in Good Shape. PJO STAINING AROUND WELL HEAD. 19.15.29						

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,


Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.