

# State of New Mexico

## Energy, Minerals and Natural Resources Department

**Susana Martinez**  
Governor

**Ken McQueen**  
Cabinet Secretary

**Matthias Sayer**  
Deputy Cabinet Secretary

**Heather Riley**  
Division Director



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

17-Jul-18

**ROVER OPERATING, LLC**  
17304 PRESTON ROAD, SUITE 300  
DALLAS TX 75252

### LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.


### INSPECTION DETAIL SECTION

BRIGHAM B No.002				M-22-17S-30E	30-015-04257-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/17/2018	Routine/Periodic	Tony Morales	Yes	No	10/20/2018	iTM1819843323
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELLHEAD 19.15.29				

FEDERAL S No.003				C-28-17S-30E	30-015-04373-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/17/2018	Routine/Periodic	Tony Morales	Yes	No	10/20/2018	iTM1819840590
Comments on Inspection:		OK. All Equipment and Location in Good Shape. PJ. TANK BATTERIES OK. OLD TANK / HEATER TREATOR ON LOCATION.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

A handwritten signature in black ink, appearing to read "Tony Morales", with a stylized flourish at the end.

Artesia OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.