## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

Heather Riley
Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

24-Jul-18

## **ENERGYQUEST II, LLC**

4526 Research Forest Dr. Suite 200 The Woodlands TX 77381-7381

**LETTER OF VIOLATION - Inspection** 

## Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

	-	INSPECTIO	N DETAIL	SECTION		
BEESON F Inspection Date	FEDERAL No.0  Type Inspection	21 Inspector	Violation?	K-31-17S-30E *Significant Non-Compliance?	30-015-29839-00-0 Corrective Action Due By:	O Inspection No.
07/24/2018	Routine/Periodic	c Tony Morales	Yes	No	10/27/2018	iTM1820544192
Comments	on Inspection: O	K. All Equipment and Location in	Good Shape.	PJO STAINING A	ROUND PJ 19.15.29	
BEESON F Inspection Date	FEDERAL No.0	22 Inspector	Violation?	H-31-17S-30E *Significant Non-Compliance?	30-015-29840-00-0 Corrective Action Due By:	O Inspection No.
07/24/2018	Routine/Periodi	c Tony Morales	Yes	No	10/27/2018	iTM1820545421
Comments		K. All Equipment and Location in 9.15.29	Good Shape.	PJO STAINING A	ROUND WELLHEAD	•
BEESON F Inspection Date	FEDERAL No.0  Type Inspection	30 Inspector	Violation?	A-31-17S-30E *Significant Non-Compliance?	30-015-31218-00-0 Corrective Action Due By:	O Inspection No.
07/24/2018	Routine/Periodic	c Tony Morales	Yes	No	10/27/2018	iTM1820548550
Comments		oK. All Equipment and Location in 9.15.29	Good Shape.	PJO STAINING A	ROUND WELLHEAD	

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OOD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.