## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McOueen

**Cabinet Secretary** 

**Matthias Sayer** 

**Deputy Cabinet Secretary** 

**Heather Riley Division Director** 



## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

02-Aug-18

## RAY WESTALL OPERATING, INC.

P.O. Box 4

Loco Hills NM 88255-8255

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO	N DETAIL	SECTION		<u> </u>
FEDERAL Inspection Date	N No.002  Type Inspection		Inspector	Violation?	P-27-18S-30E *Significant Non-Compliance?	30-015-20689-00-0 Corrective Action Due By:	O Inspection No.
08/02/2018	Routine/Period	dic	Tony Morales	Yes	No	11/5/2018	iTM1821443669
Comments	on Inspection:	OK. All Equipm 19.15.29	ent and Location in	Good Shape.	PJ. STAINING A	ROUND WELL HEAL	)
RITZ FEDE Inspection Date	ERAL No.002  Type Inspection		Inspector	Violation?	J-35-18S-30E *Significant Non-Compliance?	30-015-24798-00-0 Corrective Action Due By:	O Inspection No.
08/02/2018	Routine/Perio	dic	Tony Morales	Yes	No	11/5/2018	iTM1821447567
Comments	on Inspection:	OK. All Equipm 19.15.29	ent and Location in	Good Shape.	PJ STAINING A	ROUND WELLHEAD	
RITZ FEDE Inspection Date	ERAL No.004  Type Inspection		Inspector	Violation?	B-35-18S-30E *Significant Non-Compliance?	30-015-25142-00-0 Corrective Action Due By:	O Inspection No.
08/02/2018	Routine/Perio	dic	Tony Morales	Yes	No	11/5/2018	iTM1821446888
		OK. All Equipm 19.15.29	ent and Location ir	Good Shape.	PJ STAINING A	ROUND WELLHEAD	)

TRIGG FEDERAL No.001

K-35-18S-30E

30-015-25348-00-00

Inspection Date

Type Inspection

Inspector

Violation?

\*Significant Non-Compliance?

Corrective **Action Due By:** 

Inspection No.

08/02/2018

Routine/Periodic

**Tony Morales** 

Yes

No

11/5/2018

iTM1821446103

**Comments on Inspection:** 

OK. All Equipment and Location in Good Shape.

PJ. STAINING AROUND WELLHEAD

**TANK BATTERIES STAINING 19.15.29** 

N-35-18S-30E

30-015-25807-00-00

Inspection

Type Inspection Date

Inspector

Violation?

\*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

Routine/Periodic 08/02/2018

TRIGG FEDERAL No.005

**Tony Morales** 

Yes

No

11/5/2018

iTM1821445333

**Comments on Inspection:** 

OK. All Equipment and Location in Good Shape.

19.15.29

PJ. STAINING AROUND WELL HEAD

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCK District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.