## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

**Matthias Sayer** 

**Deputy Cabinet Secretary** 

Heather Riley Division Director



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

10-Sep-18

## BREITBURN OPERATING LP

1111 Bagby Street Suite 1600 Houston TX 77002-7002

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTION	V DETAIL	SECTION		
ARTESIA UNIT No.028 Inspection Date Type Inspection			Inspector	Violation?	M-35-17S-28E *Significant Non-Compliance?	30-015-01732-00-0 Corrective Action Due By:	Inspection No.
09/10/2018	Routine/Period	lic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825349270
Comments	on Inspection:	- ,	19.15.16.8). OPER SIGN IS NOT LEG		1E NEEDS TO BE CO	ORRECTED (QUANT	UM
ARTESIA U Inspection Date	JNIT No.029  Type Inspection		Inspector	Violation?	N-35-17S-28E *Significant Non-Compliance?	30-015-01742-00-0 Corrective Action Due By:	00 Inspection No.
09/10/2018	Routine/Period	lic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825348916
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAN	4E NEEDS TO BE CO	ORRECTED (QUANT	UM
ARTESIA U Inspection Date	JNIT No.022  Type Inspection		Inspector	Violation?	K-35-17S-28E *Significant Non-Compliance?	30-015-01747-00-( Corrective Action Due By:	00 Inspection No.
09/10/2018	Routine/Period	tic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825348613
-		• `	19.15.16.8). OPER SIGN IS NOT LEGI		ME NEEDS TO BE C	ORRECTED (QUANT	TUM .

ARTESIA UNIT No.013 Inspection Date Type Inspection		•	Inspector		F-35-17S-28E *Significant Non-Compliance?	30-015-01754-00-0 Corrective Action Due By:	O Inspection No.
09/10/2018	Routine/Perio		Gilbert Cordero	Yes	No	12/14/2018	iGC1825337209
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	IE NEEDS TO BE CO	ORRECTED (QUANT	UM
ARTESIA UNIT No.014 Inspection			Immedia	Violation?	G-35-17S-28E *Significant	30-015-01755-00-0 Corrective	Inspection No.
Date 09/10/2018	Type Inspection Routine/Perio		Inspector Gilbert Cordero	Yes	Non-Compliance? No	Action Due By: 12/14/2018	iGC1825336729
*****	on Inspection:		-		NO ME NEEDS TO BE CO		1001623330729
					<del></del>		
ARTESIA UNIT No.071					E-35-17S-28E	30-015-29862-00-0 Corrective	00
Inspection Date	Type Inspection	1	Inspector	Violation?	*Significant Non-Compliance?	Action Due By:	Inspection No.
09/10/2018	Routine/Perio	dic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825338652
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	ME NEEDS TO BE CO	ORRECTED (SBX	,
ARTESIA UNIT No.072 Inspection			3/:-1-4:0	E-35-17S-28E *Significant	30-015-29863-00-0 Corrective		
Date	Type Inspection		Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.
09/10/2018	Routine/Perio		Gilbert Cordero	Yes	No	12/14/2018	iGC1825339061
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAN	TE NEEDS TO BE C	ORRECTED (QUANT	UM
ARTESIA UNIT No.075				F-35-17S-28E	30-015-29999-00-00		
Inspection Date	Type Inspection	n	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
09/10/2018	Routine/Perio	odic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825337749
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	ATOR NAM	ME NEEDS TO BE C	ORRECTED (QUANT	UM
ARTESIA UNIT No.088					K-35-17S-28E	30-015-31488-00-0	00
Inspection Date	Type Inspection	n	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
09/10/2018	Routine/Perio	odic	Gilbert Cordero	Yes	No	12/14/2018	iGC1825348358
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	RATOR NAM	ME NEEDS TO BE C	ORRECTED (QUANT	TUM
ARTESIA UNIT No.101 Inspection					M-35-17S-28E *Significant	30-015-33285-00-0 Corrective	•
Date	Type Inspection	n	Inspector	· Violation?	Non-Compliance?	•	Inspection No.
09/10/2018	Routine/Perio		Gilbert Cordero	Yes	No	12/14/2018	iGC1825349099
Comments	on Inspection:	Well Sign (Rule RESOURCES)	19.15.16.8). OPER	RATOR NAM	ME NEEDS TO BE C	ORRECTED (QUANT	Г <b>UM</b>

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Staff Mgr

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.