## **UNITED STATES**

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to receipted the

Field Officerse Serial No.

abandoned well. Use form 3160-3 (APD) for such proposals. A TOSTA				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Gas Well Other				8. Well Name and No. CORRAL CANYON 36-25 FED COM 32H	
Name of Operator     OXY USA INCORPORATED	NDIOLA .com		9. API Well No. 30-015-44642-00-X1		
3a. Address 5 GREENWAY PLAZA SUITE HOUSTON, TX 77046-0521	No. (include area code) 685-5936		10. Field and Pool or Exploratory Area  WOLFCAMP  Wale Sage Wolfcam		
4. Location of Well (Footage, Sec., T			11. County or Parish,	State	
Sec 1 T25S R29E 561FNL 1528FWL 32.165005 N Lat, 103.941666 W Lon				EDDY COUNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) TO INDIC	ATE NATURE OF	NOTICE,	REPORT, OR OTH	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize ☐ D	idize 🗖 Deepen 🗖 Produc		ion (Start/Resume)	■ Water Shut-Off
_	☐ Alter Casing ☐ H	ydraulic Fracturing	□ Reclama	ation	■ Well Integrity
Subsequent Report	☐ Casing Repair ☐ N	ew Construction	☐ Recomp	lete	Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Pl	ug and Abandon	☐ Tempor	arily Abandon	Drilling Operations
	☐ Convert to Injection ☐ Pl	ug Back	☐ Water D	Pisposal	
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  10/24/18 RU BOP, test @ 250# low 5500# high, test 10-3/4" casing to 1500# for 30 min, good test. RIH & tag cmt @ 513', drill new formation to 598', perform FIT test to EMW=18.5ppg, good test. 10/25/18 drill 9-7/8" hole to 9857' 10/31/18. RIH & set 7-5/8" 26.4# L-80 csg @ 9849', pump 80bbl mud push spacer then cmt w/ 882sx (440bbl) PPC w/ additives 9.6ppg 2.94 yield, followed by 353sx (96bbl) PPC w/ additives 13.2ppg 1.6 yield, full returns throughout job, circ 335sx (149bbl) cmt to surface, WOC. Install pack-off, test to 10000#, good test. 11/1/18 ND BOP, install wellhead cap & release rig.  11/24/18 Skid rig back to Corral Canyon 36-25 Federal Com 32H. RU BOP, test @ 250# low 5000# high,					
test 7-5/8" casing to 3500# for	30 min, good test. Drill new formati 1/25/18 Drill 6-3/4" hole to 20718'M 1 np 80bbl mud push express then cm	on to 9862', perforn	n FIT test	•	or Record
14. I hereby certify that the foregoing is  Com  Name (Printed/Typed) DAVID ST	Electronic Submission #451062 verif For OXY USA INCORPOR Imitted to AFMSS for processing by Pl	RATED, sent to the ( RISCILLA PEREZ on	Carlsbad	System (19PP0783SE)	
Signature (Electronic S	ubmission)	Date 01/17/20	)19		
	THIS SPACE FOR FEDER	RAL OR STATE (	OFFICE US	SE	
Approved By	Title -			FEB 1 2019	
Conditions of approval, if any, are attached ertify that the applicant holds legal or equivalent would entitle the applicant to conduction	Office			athon Shepard	
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a crime for any	person knowingly and	willfully to ma	ke to any department or	agency of the United

## Additional data for EC transaction #451062 that would not fit on the form

## 32. Additional remarks, continued

13.2ppg 1.39 yield, full returns throughout job, est. TOC @ 6500', WOC. 12/6/18 RUWL RIH & set RBP @ 3005', test RBP to 1000# for 30 min, good test. 12/6/18 ND BOP, install wellhead cap, RD & release rig.

12/19/18 Notified BLM- David Mervine of intent to skid rig from Corral Canyon 36-25 Federal Com 33H to Corral Canyon 36-25 Federal Com 32H. 12/20/18 RUWL RIH & retrieve RBP @ 3005', POOH. Break test BOP, 250# low 3500# high, good. RIH w/ BHA, tag cmt @ 18250'. 12/21/18 Drill out cmt from 18250'-20588', POOH, circ bottoms up to clean out. Test casing to 3500# for 30 min, good test. 12/23/18 RUWL RIH & set 1st RBP @ 9885', test RBP to 4000# for 30 min, good test. RIH & set 2nd RBP @ 3000', test RBP to 1000# for 30 min, good test. ND BOP, Install wellhead cap, RD Rel Rig 12/23/18.