Submit One Copy To Appropriate District State of New Mexico Office	Form C-103
District I Energy, Minerals and Natural Resources	Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210  APR 2019 CONSERVATION DIVISION	30-005-61557
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION  District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87505  District IV  1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	0.0000000000000000000000000000000000000
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Wagner
PROPOSALS.)  1. Type of Well: □Oil Well ☒ Gas Well □ Other	8. Well Number 2
Name of Operator     The Eastland Oil Company	9. OGRID Number
3. Address of Operator PO Box 3488, Midland, TX, 79702	10. Pool name or Wildcat Pecos Slope
4. Well Location	1 ecos Siope
Unit Letter J: 1980 feet from the South line and 1980 feet from the East line	
Section 10 Township 7-S Range 26-E NMPM County Chaves	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3429' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOI	<del>_</del>
TEMPORARILY ABANDON	RILLING OPNS. P AND A
FULL OR ALTER CASING   MOLTIPLE COMPL   CASING/CEME	N1 30B
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed.	oved. (Poured onsite concrete bases do not have
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE Carrelly TITLE Vice President DATE 4/25/2019	
SIGNATURE CORNELLY TITLE Vice Fres	dent DATE 4/25/2019
TYPE OR PRINT NAME Garrett Donnelly E-MAIL: gdonnelly@east	andoil.com PHONE: (432)683-6293
<del>-</del>	n a
APPROVED BY: Dabon TITLE Compliance	DATE