	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAG	TERIOR	ED	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018
SUNDR	Y NOTICES AND REPOR	RTS ON WELLS		e Serial No. .C029342E
abandoned w	his form for proposals to vell. Use form 3160-3 (APE) for such proposals	6. If Inc	lian, Allottee or Tribe Name
SUBMIT II	N TRIPLICATE - Other inst	ructions on page 2	ARIESIN 7. If Un	it or CA/Agreement, Name and/or No.
abandoned well. Use form 3160-3 (APD) for such proposalsUN SUBMIT IN TRIPLICATE - Other instructions on page 2 DISTRICTII-ARIESIAG 1. Type of Well Ø Oil Well Gas Well Other			8. Well THU	Name and No. NDER ROAD FED 1
2. Name of Operator Contact: DELILAH FLORES COG OPERATING LLC E-Mail: dflores2@concho.com				Well No. 115-29910-00-S1
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		3b. Phone No. (include area code Ph: 575-748-6946		d and Pool or Exploratory Area AYBURG
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. Cou	nty or Parish, State
Sec 20 T17S R30E SWNE 2	2310FNL 2310FEL		EDD	DY COUNTY, NM
12. CHECK THE	APPROPRIATE BOX(ES)	TO INDICATE NATURE (DF NOTICE, REPOR	T, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent	🗖 Acidize	Deepen	Production (Star	r/Resume) 🔲 Water Shut-Off
	Alter Casing	Hydraulic Fracturing		Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	D Other
Final Abandonment Notice	 Change Plans Convert to Injection 	🛛 Plug and Abandon 🗖 Plug Back	Temporarily Aba Water Disposal	indon
following completion of the involvesting has been completed. Final determined that the site is ready for 05/20/19 MIRU plugging equipole w/ tbg. 05/21/19 Finish 1/2" CIBP @ 4267'. Circulate class C cmt @ 4267'. Circulate class C cmt @ 4267'. 2620'. Spotted 35 sx cmt 12 cmt @ 576' & circulated to support the support of t	ed operations. If the operation res Abandonment Notices must be file r final inspection. uipment. Tried to release pu ied POH w/ tbg & K-bars. Co ed hole w/ salt gel. Pressure Spotted 60 sx class C cmt w 00-846'. WOC 05/22/19 Ta uirface. Rigged down & mov ead, & Terry Wilson w/ BLM	ults in a multiple completion or rea d only after all requirements, inclu- mp. POH w/ rods. Dug out of build not release pump and lis a test csg, held.500_PSL_Spc // 2% CACL @ 3245-2638'. gged plug @ 820'. ND BOP red off. 05/22/19 Moved in b 1 verified cmt to surface. We	completion in a new interv iding reclamation, have be cellar, NU BOP. Bega ast joint. <u>Set 5</u> <u>tited 50 sx</u> WOC. Tagged <u>plug (c</u> Spotted 60 sx class, ackhoe and welder, elded on "Under	n RECLAMATION PROCEDURE ATTACHED
	Ac	Cepted for record - NMOO	CD	
14. I hereby certify that the foregoing	Electronic Submission #4	67147 verified by the BLM We PERATING LLC, sent to the C	Carlsbad	
	H FLORES		LATORACE	
Signature (Electroni	c Submission)			
, cliccuom		R FEDERAL OR STATE		N − 3 2019 − − −
1 <u></u>			Lomeke	nnay LIE
Approved By		Title	BUREAU O	F LAND MANAGENEINE
Conditions of approval, if any, are attac certify that the applicant holds legal or e which would entitle the applicant to cor	equitable title to those rights in the	not warrant or subject lease Office	CARLS	BAD FIELD OFFICE
Title 18 U.S.C. Section 1001 and Title 4 States any false, fictitious or frauduler				department or agency of the United

٤

(Instructions on page 2) ** BLM REVISED **

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.

7 At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos

Supervisory Petroleum Engineering Tech 575-234-5909 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialisi 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Melissa Hom Environmental Protection Specialist 575-234-5951

Kelsey Wade Evaironmental Protection Specialist 575-234-5996

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612