

Submit 1 Copy To Appropriate District Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00802
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Lime Rock Resources II-A, L.P.		6. State Oil & Gas Lease No.
3. Address of Operator 1111 Bagby Street, Suite 4600 Houston, Texas 77002		7. Lease Name or Unit Agreement Name West Red Lake Unit
4. Well Location Unit Letter <u>7</u> : <u>810</u> feet from the <u>South</u> line and <u>960</u> feet from the <u>West</u> line Section <u>06</u> Township <u>18S</u> Range <u>27E</u> NMPM NM County <u>Eddy</u>		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3381' GL		9. OGRID Number <u>277558</u>
		10. Pool name or Wildcat Redlake: Queen-Grayburg-SA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: Corrective Actions (Violation) <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

API Number has been placed on well sign.

RECEIVED

AUG 14 2019

DISTRICT IV-ARTESIA O.C.D.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael Barrett TITLE Production Superintendent DATE 08-7-19

Type or print name Michael Barrett E-mail address: mbarrett@limerockresources.com PHONE: 575-365-9724

APPROVED BY Deborah TITLE Compliance Officer DATE 8-14-19

Conditions of Approval (if any):

State Of New Mexico

Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham
Governor
Sarah Cottrell Propst
Cabinet Secretary
Todd E. Leahy, JD, PhD
Deputy Cabinet Secretary

Adrienne Sandoval
Division Director



**"Response Required - Deadline
Enclosed"**

*Field Inspection Program
"Preserving the Integrity of Our Environment"*

01-Aug-19

LIME ROCK RESOURCES II-A, L.P.
1111 Bagby Street
Suite 4600
Houston, TX 77002

LETTER OF VIOLATION - Field Inspection

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-015-00802] WEST RED LAKE UNIT #001

OGRID: 277558

M-06-18S-27E 810 FSL 960 FWL

Inspection Date	Type Inspection	Inspector	Corrective Action Due By	Inspection No.
8/1/2019	Routine Inspection	[DRS] Danny Smolik	10/30/2019	iDRS1921337438

Violations:

Rule	Violation
19.15.16.8 Sign on Wells	Inaccurate Information
Comment:	
No API number on sign	

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division * 811 S. First St. * Artesia, NM 88210
Phone: 575-748-1283 * Fax: 575-748-9720 * www.emnrd.state.nm.us