NM OIL CONSERVATION ARTESIA DISTRICT

Submit One Copy To Appropriate District 0 2 2019 Office State of	State of New Mexico			Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 88240 RECEIVED District II	Inerals and Natural Resources		Revised November 3, 2011 WELL API NO.	
District II 811 S. First St., Artesia, NM 88210 OIL CONSER	SERVATION DIVISION		30-015-26342	of Loss
District III 1220 Sout	1220 South St. Francis Dr.		5. Indicate Type STATE	FEE
District IV Santa F	Santa Fe, NM 87505		6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name of Ceniza AGZ Cor	or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number	
1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other			1	
2. Name of Operator EOG Resources, Inc.			9. OGRID Number	
3. Address of Operator			10. Pool name or Wildcat	
104 South Fourth Street, Artesia, NM 88210			North Dagger Dr	aw Upper Penn
4. Well Location				
Unit Letter P: 660 feet from the South line and 660 feet from the East line Section 2 Township 20S Range 24E NMPM Eddy County				
Section 2 Township 20S Range 24E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3608' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				ALTERING CASING [] '
TEMPORARILY ABANDON				P AND A
	_			
OTHER:				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
TERMANENTET STAMTED ON THE MARKER S SORFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment. Bur, a splast a least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. Candelilla AKD State Com #2 and the Huisache AHI State #2 wells are active and producing into the				
Ceniza AGZ Battery. Wrong Sign @ TB All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines. Active pipeline(s) within EOG Y Resources gas system. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well				
location, except for utility's distribution infrastructure.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE	_TITLE: _	Environmental Sup	ervisor	_ DATE10/2/2019
TYPE OR PRINT NAME: Robert Asher	E-MAIL:	Robert Asher@ed	ogresources.com	PHONE: <u>575-748-4217</u>
Ear State Liga Only				GC .
APPROVED BY:	TITLE	DENI	D	DATE 10/22/19
Conditions of Approval (if any):				