	abandoned wei	II. Use form 3160-3 (AP	D) for such proposals.	6. If Indian, Allotto	· · · · · · · · · · · · · · · · · · ·	
	SUBMIT IN 1	TRIPLICATE - Other ins	tructions on page 2	7. If Unit or CA/A	greement, Name and/or No.	
1. Type	of Well Dil Well 🗖 Gas Well 🔲 Oth	ner ·			8. Well Name and No. PLATINUM MDP1 34-3 FEDERAL COM 172	
2. Name	of Operator USA INCORPORATED	Contact:	SARAH CHAPMAN HAPMAN@OXY.COM	9. API Well No. 30-015-4523	1-00-X1	
3a. Add 5 GF HOU	Address GREENWAY PLAZA SUITE 110 OUSTON, TX 77046-0521		3b. Phone No. (include area code) Ph: 713-350-4997		10. Field and Pool or Exploratory Area COTTON DRAW-BONE SPRING	
	tion of Well (Footage, Sec., T.			11. County or Pari	11. County or Parish, State	
	34 T23S R31E NWNW 22 67578 N Lat, 103.771614		2	EDDY COUN	ITY, NM	
	12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR C	THER DATA	
TY	PE OF SUBMISSION		TYPE OF	ACTION		
	otice of Intent	Acidize	Deepen	Production (Start/Resume)	-	
_	ibsequent Report	Alter Casing	Hydraulic Fracturing	□ Reclamation	Well Integrity	
_	nal Abandonment Notice	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	Other Drilling Operations	
¥ 1	nai Abandonment Notice					
If the Attac follow testin deten 7/9/1 gooc Drill	proposal is to deepen direction h the Bond under which the won wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new form 12-114" hole to 4426' RIH	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re andonment Notices must be fi inal inspection. 0# high 250# low, good t nation to 625', perform FI I & set 9-5/8", 40# HCL-8	ent details, including estimated startin, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test <u>13-3/8" csg to 1500#</u> T test to EMW=19.5ppg 306ps 0 BTC csg @ 4411'. pump 80b	red and true vertical depths of all pe Required subsequent reports mus impletion in a new interval, a Form ing reclamation, have been complet <u>for 30 minutes</u> , 51, good test. bbl mudpush spacer	rtinent markers and zones. t be filed within 30 days 3160-4 must be filed once	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/2 12.8	proposal is to deepen directiona h the Bond under which the work wing completion of the involved g has been completed. Final At mined that the site is ready for final 19 MIRU, test BOP to 500 d test. RIH & drill new form 12-1/4" hole to 4426'. RIH cmt w/ 1191sxs (364bbl) s C w/ additives 14.8ppg ' /19 MIRU, test BOP to 50 d test. RIH & drill new form 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a	eration: Clearly state all pertime ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good t nation to 625', perform FI 4 & set 9-5/8". 40# HCL-80 class C w/ additives 12.9 1.33 yield. Full returns thr 00# high 250# low, good nation to 4436', perform FI 4 & set 7-5/8" HCL-80 FJ, additives 13.2ppg 1.61 yis surface. Ran echometer,	ent details, including estimated startim, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test $13-3/8" \operatorname{csg}$ to $1500\#$ T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 4411</u> ', pump 80t ppg 1.73 yield followed by 16 oughout job, circ 150bbl cmt to test. Test $9-5/8" \operatorname{csg}$ to $2500\#$ 'IT test to EMW=14.5ppg 699r 'SF csg @ 10638', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, bl mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, osi, good test. I spacer then cmt w/ additives // 2bbl cmt. Full	thent markers and zones. the filed within 30 days 3160-4 must be filed once ed and the operator has L CONSERVATION RTESIA DISTRICT SEP 2 3 2019	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/ 2 12.8 retur	proposal is to deepen directiona h the Bond under which the work wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new form 12-1/4" hole to 4426'. RIH cmt.w/.1191sxs (364bbl) s C w/ additives 14.8ppg ' /19 MIRU, test BOP to 50 d test. RIH & drill new form 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a ppg 1.96 yield, no cmt to s rns, cmt to surface. 7/25/1	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good t nation to 625', perform FI 4 & set <u>9-5/8" 40# HCL-80</u> class C w/ additives 12.9 1.33 yield. Full returns thr 00# high 250# low, good nation to 4436', perform FI 4 & set <u>7-5/8" HCL-80 FJ</u> , additives 13.2ppg 1.61 yi surface. Ran echometer, 9 D and rig release.	ent details, including estimated startin, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test <u>13-3/8" csg to 1500#</u> T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 4411</u> ', pump 80t pog 1.73 yield followed by 16 oughout job, circ 150bbl cmt to test. Test <u>9-5/8" csg to 2500#</u> 'IT test to EMW=14.5ppg 699f <u>/SF csg @ 10638</u> ', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, bl mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, osi, good test. I spacer then cmt w/ additives // 2bbl cmt. Full	the filed within 30 days 3160-4 must be filed once ed and the operator has L CONSERVATION RTESIA DISTRICT	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/ 2 12.8 retur	proposal is to deepen directiona h the Bond under which the wor wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new forn 12-1/4" hole to 4426'. RIH cmt w/ 1191sxs (364bbl) s C w/ additives 14.8ppg /19 MIRU, test BOP to 50 d test. RIH & drill new forn 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a ppg 1.96 yield, no cmt to rns, cmt to surface. 7/25/1	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good t nation to 625', perform FI 1 & set <u>9-5/8" 40# HCL-8</u> class C w/ additives 12.9 1.33 yield. Full returns thr 00# high 250# low, good nation to 4436', perform FI 1 & set <u>7-5/8" HCL-80 FJ</u> , additives 13.2ppg 1.61 yi surface. Ran echometer, 9 D and rig release.	ent details, including estimated startin give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test 13-3/8" csg to 1500# T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 4411</u> ', pump 80t <u>0 ppg 1.73 yield followed by 165</u> oughout job, circ 150bbl cmt ta test. Test 9-5/8" csg to 2500# T test to EMW=14.5pp 699g <u>/SF csg @ 10638</u> ', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w <u>C C / 0</u> Accepted for reco	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, 51, good test. bbl mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, 53, good test. I spacer then cmt W additives 2bbl cmt. Full 2bbl cmt. Full A the NMOCD	the filed within 30 days 3160-4 must be filed once ed and the operator has L CONSERVATION RTESIA DISTRICT SEP 2 3 2019	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/ 2 12.8 retur	proposal is to deepen directiona h the Bond under which the wor wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new forn 12-1/4" hole to 4426'. RIH cmt w/ 1191sxs (364bbl) s C w/ additives 14.8ppg /19 MIRU, test BOP to 50 d test. RIH & drill new forn 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a ppg 1.96 yield, no cmt to rns, cmt to surface. 7/25/1	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good to nation to 625', perform FI t & set <u>9-5/8".40# HCL-80</u> class C w/ additives 12.6 class C w/ addi	ent details, including estimated startim, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test 13-3/8" csg to 1500# T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 441</u> 1', pump 80t Oppg 1.73 yield followed by 16 oughout job, circ 150bbl cmt to test. Test 9-5/8" csg to 2500# FIT test to EMW=14.5ppg 699f /SF csg @ 10638', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w Accepted for reco 4479615 verified by the BLM Wel A INCORPORATED, sent to the ressing by PRISCILLA PEREZ of	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, 51, good test. bbl mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, 53, good test. I spacer then cmt W additives 2bbl cmt. Full 2bbl cmt. Full A the NMOCD	the filed within 30 days 3160-4 must be filed once ed and the operator has L CONSERVATION RTESIA DISTRICT SEP 2 3 2019	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/ 2 12.8 retur	proposal is to deepen directiona h the Bond under which the woi wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new forn 12-1/4" hole to 4426'. RIH crnt w/ 1191sxs (364bbl) s C w/ additives 14.8ppg ' /19 MIRU, test BOP to 50 d test. RIH & drill new forn 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a ppg 1.96 yield, no cmt to s rns, cmt to surface. 7/25/1 reby certify that the foregoing is (<i>Printed/Typed</i>) SARAH C	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good t nation to 625', perform FI t & set <u>9-5/8" 40# HCL-80</u> class C w/ additives 12.5 class C w/ addit	ent details, including estimated startim, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test 13-3/8" csg to 1500# T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 441</u> 1', pump 80t Oppg 1.73 yield followed by 16 oughout job, circ 150bbl cmt to test. Test 9-5/8" csg to 2500# FIT test to EMW=14.5ppg 699f /SF csg @ 10638', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w Accepted for reco 4479615 verified by the BLM Wel A INCORPORATED, sent to the ressing by PRISCILLA PEREZ of	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, 51, good test. bbl mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, 5si, good test. I spacer then cmt W additives 2bbl cmt. Full 2bbl cmt. Full 2bbl cmt. Full 1 Information System Carlsbad n 08/22/2019 (19PP3034SE) ATORY SPECIALIST	the filed within 30 days 3160-4 must be filed once ed and the operator has L CONSERVATION RTESIA DISTRICT SEP 2 3 2019	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/ 2 12.8 retur 14. I her Name	proposal is to deepen directiona h the Bond under which the woi wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new forn 12-1/4" hole to 4426'. RIH crnt w/ 1191sxs (364bbl) s C w/ additives 14.8ppg ' /19 MIRU, test BOP to 50 d test. RIH & drill new forn 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a ppg 1.96 yield, no cmt to s rns, cmt to surface. 7/25/1 reby certify that the foregoing is (<i>Printed/Typed</i>) SARAH C	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good t nation to 625', perform FI 1 & set <u>9-5/8".40# HCL-80</u> class C w/ additives 12.9 1.33 yield. Full returns thr 00# high 250# low, good nation to 4436', perform FI 1 & set <u>7-5/8" HCL-80 FJ</u> additives 13.2ppg 1.61 yi surface. Ran echometer, 9 D and rig release. strue and correct. Electronic Submission # For OXY US mmitted to AFMSS for proc HAPMAN Submission)	ent details, including estimated startim, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test 13-3/8" csg to 1500# T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 4411</u> ', pump 80t ppg 1.73 yield followed by 16 oughout job, circ 150bbl cmt tr test. Test 9-5/8" csg to 2500# FIT test to EMW=14.5ppg 699f /SF csg @ 10638', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w C C / 0 Accepted for reco the start of the start of the cessing by PRISCILLA PEREZ of Title REGUL	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, bil mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, Si, good test. I spacer then cmt W additives W additives W additives M 2bbl cmt. Full I Information System Carlsbad n 08/22/2019 (19PP3034SE) ATORY SPECIALIST	thent markers and zones. the filed within 30 days 3160-4 must be filed once ed and the operator has L CONSERVATION RTESIA DISTRICT SEP 2 3 2019	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/ 2 12.8 retur 14. 1 her Signa	proposal is to deepen directiona h the Bond under which the won wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new form 12-1/4" hole to 4426'. RIH cmt w/ 1191sxs (364bbl) s C w/ additives 14.8ppg ' /19 MIRU, test BOP to 50 d test. RIH & drill new form 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a ppg 1.96 yield, no cmt to rns, cmt to surface. 7/25/1 reby certify that the foregoing is con e(Printed/Typed) SARAH C ature (Electronic S	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good t nation to 625', perform FI 1 & set <u>9-5/8".40# HCL-80</u> class C w/ additives 12.9 1.33 yield. Full returns thr 00# high 250# low, good nation to 4436', perform FI 1 & set <u>7-5/8" HCL-80 FJ</u> additives 13.2ppg 1.61 yi surface. Ran echometer, 9 D and rig release. strue and correct. Electronic Submission # For OXY US mmitted to AFMSS for proc HAPMAN Submission)	ent details, including estimated startim, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test 13-3/8" csg to 1500# T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 4411</u> ', pump 80t 0 ppg 1.73 yield followed by 16' oughout job, circ 150bbl cmt ta test. Test 9-5/8" csg to 2500# T test to EMW=14.5pp 699g (SF csg @ 10638', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w CC C / O Accepted for reco tatted the REGUL Date 08/21/2 OR FEDERAL OR STATE	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, bil mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, Si, good test. I spacer then cmt W additives W additives W additives M 2bbl cmt. Full I Information System Carlsbad n 08/22/2019 (19PP3034SE) ATORY SPECIALIST	the filed within 30 days 3160-4 must be filed once ed and the operator has L CONSERVATION RTESIA DISTRICT SEP 2 3 2019	
If the Attac follow testin deten 7/9/1 good Drill then class 7/16 good Drill w/ 2 12.78 retur 14. Then 14. Then Signa	proposal is to deepen directiona h the Bond under which the won wing completion of the involved g has been completed. Final At mined that the site is ready for fi 19 MIRU, test BOP to 500 d test. RIH & drill new form 12-1/4" hole to 4426'. RIH cmt w/ 1191sxs (364bbl) s C w/ additives 14.8ppg ' /19 MIRU, test BOP to 50 d test. RIH & drill new form 8-3/4" hole to 10658'. RIH 73sxs (78bbl) class H w/ a ppg 1.96 yield, no cmt to rns, cmt to surface. 7/25/1 reby certify that the foregoing is con e(Printed/Typed) SARAH C ature (Electronic S	eration: Clearly state all pertine ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re- bandonment Notices must be fi- inal inspection. 0# high 250# low, good t nation to 625', perform FI 4 & set <u>9-5/8" 40# HCL-80</u> class C w/ additives 12.9 1.33 yield. Full returns thr 00# high 250# low, good nation to 4436', perform FI 4 & set <u>7-5/8" HCL-80 FJ</u> additives 13.2ppg 1.61 yi surface. Ran echometer, 9 D and rig release. strue and correct. Electronic Submission # For OXY US mmitted to AFMSS for proc HAPMAN Submission) THIS SPACE F6	ent details, including estimated startim, give subsurface locations and measu the Bond No. on file with BLM/BIA sults in a multiple completion or reco led only after all requirements, includ est. Test 13-3/8" csg to 1500# T test to EMW=19.5ppg 306ps <u>0 BTC csg @ 4411</u> ', pump 80t 0ppg 1.73 yield followed by 16' oughout job, circ 150bbl cmt to test. Test 9-5/8" csg to 2500# T test to EMW=14.5pp 699g /SF csg @ 10638', pump 40bb eld followed by 752sxs class H TOC @ 34', perform top job w CC / 0 Accepted for rece tar9615 verified by the BLM Well A INCORPORATED, sent to the testing by PRISCILLA PEREZ of Title REGUL Date 08/21/2 DR FEDERAL OR STATE	g date of any proposed work and ap red and true vertical depths of all pe Required subsequent reports musi- impletion in a new interval, a Form ing reclamation, have been complet for 30 minutes, 51, good test. bil mudpush spacer 7sxs (40bbl) o surface. for 30 minutes, 53, good test. I spacer then cmt W additives 2bbl cmt. Full 2bbl cmt. Full 2bbl cmt. Full 2bbl cmt. Full 2bbl cmt. Full 2bbl cmt. Full 2bbl cmt. Sull 2bbl cmt. Sull cmt. Sull 2bbl cmt. Sull	The t	

Additional data for EC transaction #479615 that would not fit on the form

32. Additional remarks, continued

8/2/19 MIRU, test BOP to 5000# high 250# low, good test. Test 7/5-8" csg to 4000# for 30 minutes, good test. RIH & drill new formation to 10668', perform FIT test to EMW=15.0ppg 1765#, good test. Drill 6-3/4" hole to 11247'V/21405'M. RIH & set 5-1/2" 20# P-110 DQX/TORQ DQW @ 21405' pump 120bbl mudpush spacer then cmt w/ 816sxs (204bbl) class H w/ additives 13.2ppg 1.38 yield. Full returns throughout job, TOC @ ~10100'. 8/13/19 ND BOP, cut csg, install nightcap and rig release.