Form \$160.5 (June 2015)

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS IN SEASON FIELD

SUNDRY NOTICES AND REPORTS IN SEASON FIEL

abandoned well. Use form 3160-3 (APD) for such properties as					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well     Gas Well □ Other					8. Well Name and No. PLATINUM MDP1 34-3 FEDERAL COM 176		
Name of Operator Contact: SARAH CHAPMAN     OXY USA INCORPORATED E-Mail: SARAH_CHAPMAN@OXY.COM					9. API Well No. 30-015-45233-00-X1		
3a. Address 5 GREENWAY PLAZA SUITE 110 HOUSTON, TX 77046-0521  3b. Phone No Ph: 713-35					10. Field and Pool or Exploratory Area PURPLE SAGE-WOLFCAMP (GAS)		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. Co	11. County or Parish, State		
Sec 34 T23S R31E NENE 110FNL 1003FEL 32.267887 N Lat, 103.760368 W Lon					EDDY COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE N	ATURE OI	F NOTICE, REPO	RT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	Deepen		☐ Production (Start/Resume)		■ Water Shut-Off	
<del>-</del>	☐ Alter Casing	☐ Hydraulic	lic Fracturing			■ Well Integrity	
Subsequent Report     ☐	□ Casing Repair	■ New Cons	ruction	☐ Recomplete		Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Plug and Abandon ☐ To		□ Temporarily Al	orarily Abandon Drilling Operations			
•	□ Convert to Injection	☐ Convert to Injection ☐ Plug Back ☐ W		■ Water Disposal			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  6/24/19 MIRU, test BOP to 5000# high 250# low, good test. Test 13-3/8" csq to 1500# for 30 minutes, good test. RIH & drill new formation to 707', perform FIT test to EMW=9.6ppg 317psi, good test. Drill 12-1/4" hole to 4465'. RIH & set 9-5/8" 40# HCL-80 csq @ 4455', pump 80bbl mudpush spacer then cmt w/ 1191sxs (365bbl) class C w/ additives 14.8ppg 1.33 yield. Full returns throughout job, circ 127bbl cmt to surface.  6/27/19 RD and rig release. 7/9/2019 MIRU, test BOP to 5000# high 250# low, good test. Test 9-5/8" csq to 1500# for 30 minutes, good test. RIH & drill new formation to 4475', perform FIT test to EMW=14.5ppg 1350# good test. Drill 8-1/2" hole to 10947' RIH & set 7-5/8" HCL-80 FJ/SF csg @ ARTESIA DISTRICT 10957' pump 40bbl mudpush spacer then cmt w/ 226sxs (59bbl) class H w/ additives 13.2ppg 1.75  yield, wait on cement for 2 hours. Run planned 2nd stage job w/ 331sxs class H w/ additives 12.8ppg 1.75  yield, full returns throughout job, circ 23bbl cmt to surface.  RECEIVED  RECEIVED							
	Electronic Submission #478: For OXY USA IN nmitted to AFMSS for processi	CORPORATEĎ,	sent to the A PEREZ or	Carlsbad n 08/19/2019 (19PP3	000SE)		
Name (Printed/Typed) SARAH CHAPMAN			REGUL	ATORY SPECIAL	ST		
Signature (Electronic	Submission)	Date	08/15/20	019			
	THIS SPACE FOR	FEDERAL OF	STATE	OFFICE USE	•	,	
Approved By			Title Accepted for Record		AUG <sub>ate</sub> 2 2 2019		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				nathon Shepard risbad Field Office		<u> </u>	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crin statements or representations as to a	ne for any person k ny matter within its	nowingly and jurisdiction.	willfully to make to ar	y department o	or agency of the United	

## Additional data for EC transaction #478348 that would not fit on the form

## 32. Additional remarks, continued

7/24/19 MIRU, test BOP to 5000# high 250# low, good test. Test 7-5/8" to 4000# for 30 minutes, good test. RIH & drill new formation to 10957', perform FIT test to EMW=11.9ppg 1766psi, good test. Drill 6-3/4" hole to 11089'V/21877'M. RIH & set 5-1/2" 20# P-110 DQX/TORQ DQW csg @ 21877', pump 120bbl mudpush spacer then cmt/ w/ 775sxs (207bbl) class H w/ additives 13.2ppg 1.38 yield. Full returns throughout job, TOC @ 10445'. 8/5/19 ND BOP, cut csg, install nightcap and rig release.