Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR ISDAM FIELD OF FIRESE Serial No. BUREAU OF LAND MANAGEMENT ISDAM FIELD OF FIRESE SERIAL NO. WHINMAS5607

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS TO A POLICE AND REPORTS ON WELLS TO A POLICE AND A POLICE AN

6 If Indian Allottee or Tribe Na

abandoned well. Use form 3160-3 (APD) for such proposals.					o. II mulan, Anouce o	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. ROSS DRAW 25 36 FED COM 72H	
Name of Operator					9. API Well No. 30-015-45586-00-X1	
3a. Address 6401 HOLIDAY HILL ROAD B MIDLAND, TX 79707	(include area code) 1.7379		10. Field and Pool or Exploratory Area PURPLE SAGE-WOLFCAMP (GAS) WILDCAT - BONE SPRING			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
Sec 25 T26S R29E NENW 170FNL 2101FWL					EDDY COUNTY, NM	
\						
12. CHECK THE AF	PPROPRIATE BOX(ES) T	O INDICA	TE NATURE OI	F NOTICE, F	REPORT, OR OTI	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	_		. –		on (Start/Resume)	■ Water Shut-Off
Subsequent Report ■ Subsequent Report Subsequent Report			aulic Fracturing Reclam			☐ Well Integrity
	, -		Construction Recom			Other Drilling Operations
☐ Final Abandonment Notice	Change Plans		and Abandon		rily Abandon	Drining Operations
			Back	☐ Water Disposal nated starting date of any proposed work a		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 04/16/19 - 04/17/19 Spud 17-1/2" hole. TD hole @ 630'. Run 13-3/8", J55, 54.5# csq to 629'. LEAD CMT: 671 sx (195 bbls) Class C. TAIL CMT: 471 sx (112 bbls) Class C. Bump plug. Returned 131 bbls cmt to surface. 04/18/19 - 04/19/19 Test Head flange, spool, blind rams, HCR, choke, floor valves, IBOP and kill valves 250/10000. Test annular 250/3500. Stand pipes and pumps 250 low, 5000 high. Accumulator draw down test. (all good). Test csg to 1500 psi (good). Drill cmt and float equipment. Drill 12-1/4" hole. SEP 2 3 2019						
TD 12-1/4" hole @ 3021'. Run 9-5/8", J55, 40# csg to 3011'. LEAD CMT: 1932 sxs (563 bbls) Class C. TAIL CMT: 260 sx (57 bbls) Class H. Bump plug. Returned 450 bbls cmt to surface.						
14. I hereby certify that the foregoing is	Electronic Submission #48	Y INCORPO I	RATED. sent to th	ne Carlsbad	•	
Name (Printed/Typed) TRACIE J	Title REGUL	ATORY ANA	LYST ·	· · · · · · · · · · · · · · · · · · ·		
Signature (Electronic S	Date 08/30/20	019				
	THIS SPACE FOR	R FEDERA	L OR STATE (OFFICE US	E	
Approved By		·	Title Acce	ented for	r Record	SEP 1 0 2019
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			j.	onathon Sl Carlsbad Field	hepard	·
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to mak	te to any department or	agency of the United

Additional data for EC transaction #481446 that would not fit on the form

32. Additional remarks, continued

04/22/2019

Drill cmt and float equipment. Drill 8-3/4" hole.

05/1/19

TD hole @ 9277'. Run 7", 32# CYP110 csg to 9267'. LEAD CMT; 478 sx (216 bbls) Class C followed with 606 sx (122 bbls) Poz/C. TAIL CMT: 275 sx (57 bbls) Class H. Bump plug. Return 110 bbls cmt to surface. Secure well. Walk rig off.

06/01/19 - 06/02/19

Test choke manifold, HCR, rams, Inside Manual HCR, kill valves, floor valves, blind rams, manual I-BOP 250/10000 10 min (good). Test annular 250/3500 psi 10 min (good). Perform accumulator draw down test & sizing check (good). Test csg to 2400. Drill cmt & float equipment. Drill 6" hole.

TD hole @ 15806'. Run 4-1/2", 13.50# P110 liner 8251'-15,806'. Cement w/450 sx (90 bbls) Class C and 73 sx (143) 50/50 Poz. Circulate 26 bbls cmt to surface. Test liner top to 1471 psi, held 5 minutes (good)

06/08/2109

Relase rig.