Submit One Copy To Appropriate District Office District I	Form C-103
District I Resource	Revised November 3, 2011
1625 N French Dr. Hobbs NM 88240	I WELL APLNO
District II 811 S. First St., Artesia, NM 88210	N 30-015-26112 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8741 EMNRD-OCD ARTES Manarcis Dr. District IV	STATE FEE
	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	 7. Lease Name or Unit Agreement Name Parkway Delaware Unit
1. Type of Well: Oil Well Gas Well Other	8. Well Number 101
2. Name of Operator Colgate Operating, LLC	9. OGRID Number 371449
3. Address of Operator	10. Pool name or Wildcat
303 West Wall Street, Suite 700- Midland, Texas 79701	Parkway; Delaware
4. Well Location	•• •
Unit Letter <u>O</u> : <u>330</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>Eas</u>	
Section <u>26</u> Township <u>198</u> Range <u>29E</u> NMPM County <u>Edd</u>	
11. Elevation (Show whether DR, RKB, RT, G 3326 GR	R, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Qt	her Data
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE COMPL CASING/CI OTHER: D Location	CE DRILLING OPNS P AND A
All pits have been remediated in compliance with OCD rules and the terms of the	ne Operator's pit permit and closure plan.
All pits have been remediated in compliance with OCD rules and the terms of th Rat hole and cellar have been filled and leveled. Cathodic protection holes have A steel marker at least 4" in diameter and at least 4' above ground level has been	
ODEDATOD NAME LEASE NAME WELL NUMBED ADDINUMDE	D. OLIADTED/OLIADTED LOCATION OD
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORM	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour an	
other production equipment. The share been cut off at least two feet below	w ground level.
Anchors, dead men, tie down's and risers have been cut off at least two feet belo If this is a one-well lease or last remaining well on lease, the battery and pit loca	ation(s) have been remediated in compliance with
OCD rules and the terms of the Operator's pit permit and closure plan. All flow line	s, production equipment and junk have been removed
from lease and well location. South Road All metal bolts and other materials have been removed. Portable bases have been	n removed (Poured onsite concrete bases do not have
to be removed.)	in removed. (i oured onsite concrete bases do not nave
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 N retrieved flow lines and pipelines.	NMAC. All fluids have been removed from non-
If this is a one-well lease or last remaining well on lease: all electrical service po	oles and lines have been removed from lease and well
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office	e to schedule an inspection.
he and and	
SIGNATURE TITLE: Operatio	ns Tech DATE: 0/08/20
TYPE OR PRINT NAME: Mikah Thomas E-MAIL: mthomas@colgat	teenergy.com PHONE: 432-695-4272
For State Use Only	IFD GC
For State Use Only APPROVED BY: DENIED TITLE DEN	DATE 1/27/20
APPROVED BY: TITLE TITLE	DATE 1/21/20

APPROVED BY: Conditions of Approval (if any):

.