Submit One Copy To Appropriate District Office District Energy, Minerals and Natur	·
District II	WELL API NO.
811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd. Aztec NM 87410	5. Indicate Type of Lease
District IV Santa Fe, NM 875	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	LG-155
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUID DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	WIDDOW CREDIT DITATE
1. Type of Well: ☐Oil Well ☐ Gas Well ☐ Other	8. Well Number 7
2. Name of Operator GRIZZLY OPERATING LLC	9. OGRID Number
3. Address of Operator 5847 SAN FELIPE ST SUITE 3000 HOUSTON, TX 77057	10. Pool name or Wildcat PECOS SLOPE; ABO
4. Well Location	
Unit Letter G: 1980 feet from the NORTH line and 1980 feet from the EAST line Section 30 Township 4S Range 25E NMPM County CHAVES	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3916' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
	REMEDIAL WORK ALTERING CASING
	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER: D D Location is ready for OCD inspection after P&A	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR</u> <u>PERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u>	
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE MISSISTED TITLE PRODUCTION SUPERINTENDENT DATE 03/05/2020	
TYPE OR PRINT NAME <u>C.M. BLOODWORTH, P.E.</u> E-MAIL: <u>mbloodworth@vnrenergy.com</u> PHONE: <u>432-770-9738</u> For State Use Only	
APPROVED BY TITLE 2%	14H Mg- DATE 3/13/20
Conditions of Approval (if any):	7/