Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

	BUREAU OF LAND MANAGEMENT		5. Lease Serial No.
SUNDRY	NOTICES AND REPORTS C	N WELLS	NM-031963
Do not use t	this form for proposals to drill or vell. Use Form 3160-3 (APD) for s	to re-enter an	6. If Indian, Allottee or Tribe Name
SUBMIT IN TR	RIPLICATE- Other instructions o	n reverse side.	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Coll Well	Gas Well Other	· · · · · · · · · · · · · · · · · · ·	8. Well Name and No.
Name of Operator Pogo 1	Producing Company		Sunrise 8 Federal #3 9. API Well No.
3a Address P. 0. Box 10340, Midla	i i	o. (include area code) i=8100	30-015-34900 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec.,	, T., R., M., or Survey Description)		Sand Dunes Delaware West
660' FNL & 990' FEL,	Section 8, T24S, R31E $$	NFIDENTIAL	11. County or Parish, State Eddy County, NM
12. CHECK A	APPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
Notice of Intent	Acidize Deepen Alter Casing Fracture T	Production (Star	Well Integrity
x Subsequent Report	Casing Repair New Cons Change Plans Plug and A	'	× Other Drig operations
Final Abandonment Notice	Change Plans Plug and A		RUGOII
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read		ce locations and measured and true on file with BLM/BIA. Require tiple completion or recompletion in all requirements, including reclama	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read mediate Csg — Drld 11" hole mt plug. Re-drill 11" secti 00 sks Cl C Neat cmt plug. ks C 65:35 POZ @ 12.8 p hrs 09/15/06. WOC 24 hrs	rectionally or recomplete horizontally, give subsurfathe work will be performed or provide the Bond Nonvolved operations. If the operation results in a multinal Abandonment Notices shall be filed only after by for final inspection.) e to 4185'. TD reached @ 05:00 hrs. on of hole. Attempted to run interm. Redrilled. Reached TD of 4180' app followed by 200 sks Cl "C" + 195. Make cut-off. Install WH. NU E	ce locations and measured and true on file with BLM/BIA. Require tiple completion or recompletion in all requirements, including reclama is 08/11/06. Attempt to a mediate csg. Failed agai an 09/14/06. Ran 96 jts on 09/14/06. Ran 96 jts on CaCl2 @ 14.8 ppg. 0 BOP's & test to 2000# o	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has run intermediate csg. Failed. Spot 300 sks in. Got approval to plug back & sidetrack. is 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ Circ 225 sks to surface. Plug down @ ok. Test csg to 1500# for 30 mins ok.
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read mediate Csg — Drld 11" hole mediate Csg — Drld 11" section of the site is read mediate Csg — Drld 11" section of the site is read mediate Csg — Drld 11" hole mediate Csg — Drld 11" section of the site is read mediate Csg — Drld 11" hole mediate Csg — Drld 11" section of the site is read mediate Csg — Drld 11" hole mediate Csg — Drld 7-7 mediate Cs	rectionally or recomplete horizontally, give subsurfathe work will be performed or provide the Bond Nonvolved operations. If the operation results in a multinal Abandonment Notices shall be filed only after the formal inspection.) The to 4185'. TD reached @ 05:00 hrs on of hole. Attempted to run interm. Redrilled. Reached TD of 4180's pg followed by 200 sks Cl "C" + 195. Make cut-off. Install WH. NU Ent'd 1st stage w/ 600 sks Cl C @ 14. Cmt'd 3rd stage w/ 300 sks Cl C 65. Test csg to 3000# ok. Ran CBL 16.	ce locations and measured and true of on file with BLM/BIA. Require tiple completion or recompletion in all requirements, including reclams of 08/11/06. Attempt to a mediate csg. Failed agai on 09/14/06. Ran 96 jts of CaCl2 @ 14.8 ppg. C OP's & test to 2000# o 0:30 hrs 09/24/06. Log 1 ppg. Circ 40 sks to st 5:35 POZ @ 12.4 ppg fo	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has run intermediate csg. Failed. Spot 300 sks in. Got approval to plug back & sidetrack. is 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ Circ 225 sks to surface. Plug down @ ik. Test csg to 1500# for 30 mins ok. gged well w/ Halliburton. Ran 182 jts urface. Cmt'd 2 nd stage w/ 600 sks Cl C @
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read mediate Csg — Drld 11" hole mt plug. Re-drill 11" secti- 00 sks Cl C Neat cmt plug. mks C 65:35 POZ @ 12.8 p hrs 09/15/06. WOC 24 hrs Production Csg — Drld 7-7, 15.5# & 17# J-55 csg. Cm pg. Circ 60 sks to surface.	rectionally or recomplete horizontally, give subsurfathe work will be performed or provide the Bond Nonvolved operations. If the operation results in a multinal Abandonment Notices shall be filed only after the formal inspection.) The to 4185'. TD reached @ 05:00 hrs on of hole. Attempted to run interm. Redrilled. Reached TD of 4180's pg followed by 200 sks Cl "C" + 195. Make cut-off. Install WH. NU Ent'd 1st stage w/ 600 sks Cl C @ 14. Cmt'd 3rd stage w/ 300 sks Cl C 65. Test csg to 3000# ok. Ran CBL 16.	ce locations and measured and true of on file with BLM/BIA. Require tiple completion or recompletion in all requirements, including reclams of 08/11/06. Attempt to a mediate csg. Failed agai on 09/14/06. Ran 96 jts of CaCl2 @ 14.8 ppg. C OP's & test to 2000# o 0:30 hrs 09/24/06. Log 1 ppg. Circ 40 sks to st 5:35 POZ @ 12.4 ppg fo	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has run intermediate csg. Failed. Spot 300 sks in. Got approval to plug back & sidetrack. is 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ Circ 225 sks to surface. Plug down @ isk. Test csg to 1500# for 30 mins ok. gged well w/ Halliburton. Ran 182 jts urface. Cmt'd 2 nd stage w/ 600 sks Cl C @ iollowed by 200 sks Cl C + 1% CaCl2 @ 200/10/10/10/10/10/10/10/10/10/10/10/10/1
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read neediate Csg — Drld 11" hole mt plug. Re-drill 11" secti- 00 sks Cl C Neat cmt plug. sks C 65:35 POZ @ 12.8 p hrs 09/15/06. WOC 24 hrs Production Csg — Drld 7-7/ 15.5# & 17# J-55 csg. Cm pg. Circ 60 sks to surface. pg. Circ 62 sks to surface.	rectionally or recomplete horizontally, give subsurfathe work will be performed or provide the Bond Nonvolved operations. If the operation results in a multinal Abandonment Notices shall be filed only after the formal inspection.) The to 4185'. TD reached @ 05:00 hrs on of hole. Attempted to run interm. Redrilled. Reached TD of 4180's pg followed by 200 sks Cl "C" + 195. Make cut-off. Install WH. NU Ent'd 1st stage w/ 600 sks Cl C @ 14. Cmt'd 3rd stage w/ 300 sks Cl C 65. Test csg to 3000# ok. Ran CBL 16.	ce locations and measured and true of on file with BLM/BIA. Require tiple completion or recompletion in all requirements, including reclams of 08/11/06. Attempt to a mediate csg. Failed agai on 09/14/06. Ran 96 jts of CaCl2 @ 14.8 ppg. C OP's & test to 2000# o 0:30 hrs 09/24/06. Log 1 ppg. Circ 40 sks to st 5:35 POZ @ 12.4 ppg fo	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has run intermediate csg. Failed. Spot 300 sks in. Got approval to plug back & sidetrack. Is 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ Circ 225 sks to surface. Plug down @ Isk. Test csg to 1500# for 30 mins ok. Isgged well w/ Halliburton. Ran 182 jts urface. Cmt'd 2 nd stage w/ 600 sks Cl C @ Islands of the color of the c
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read neediate Csg — Drld 11" hole mt plug. Re-drill 11" section 00 sks Cl C Neat cmt plug. ks C 65:35 POZ @ 12.8 p hrs 09/15/06. WOC 24 hrs Production Csg — Drld 7-7/ 15.5# & 17# J-55 csg. Cm pg. Circ 60 sks to surface. pg. Circ 62 sks to surface. 14. Thereby certify that the fore Name (Printed/Typed)	rectionally or recomplete horizontally, give subsurfathe work will be performed or provide the Bond Nonvolved operations. If the operation results in a multinal Abandonment Notices shall be filed only after thy for final inspection.) The to 4185'. TD reached @ 05:00 hrs on of hole. Attempted to run internounce and the performed by 200 sks C1 "C" + 195. Make cut-off. Install WH. NU Entry hole to 8250'. TD reached @ 2 ant'd 1st stage w/ 600 sks C1 C @ 14. Cmt'd 3rd stage w/ 300 sks C1 C 65. Test csg to 3000# ok. Ran CBL 10 egoing is true and correct	ce locations and measured and true on file with BLM/BIA. Require iple completion or recompletion in all requirements, including reclama is 08/11/06. Attempt to a mediate csg. Failed agai on 09/14/06. Ran 96 jts is CaCl2 @ 14.8 ppg. CaCl2 @ 12.4 ppg for including the cacCl2 @ 12.4 ppg for including the caCl2 @ 12.4 ppg for including the ca	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has run intermediate csg. Failed. Spot 300 sks in. Got approval to plug back & sidetrack. Is 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ Circ 225 sks to surface. Plug down @ ok. Test csg to 1500# for 30 mins ok. gged well w/ Halliburton. Ran 182 jts urface. Cmt'd 2 nd stage w/ 600 sks Cl C @ ollowed by 200 sks Cl C + 1% CaCl2 @ RECEIVED OCD - ARTESIA
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read neediate Csg — Drld 11" hole mt plug. Re-drill 11" secti- 00 sks Cl C Neat cmt plug. ks C 65:35 POZ @ 12.8 p hrs 09/15/06. WOC 24 hrs Production Csg — Drld 7-7/ 15.5# & 17# J-55 csg. Cm pg. Circ 60 sks to surface. pg. Circ 62 sks to surface. 14. Thereby certify that the fore Name (Printed/Typed) Cathy Wright	rectionally or recomplete horizontally, give subsurfathe work will be performed or provide the Bond Nonvolved operations. If the operation results in a multinal Abandonment Notices shall be filed only after the formal inspection.) The to 4185'. TD reached @ 05:00 hrs on of hole. Attempted to run interm. Redrilled. Reached TD of 4180's pg followed by 200 sks Cl "C" + 195. Make cut-off. Install WH. NU Ent'd 1st stage w/ 600 sks Cl C @ 14. Cmt'd 3rd stage w/ 300 sks Cl C 65. Test csg to 3000# ok. Ran CBL 16.	ce locations and measured and true on file with BLM/BIA. Require iple completion or recompletion in all requirements, including reclama is 08/11/06. Attempt to a mediate csg. Failed agai on 09/14/06. Ran 96 jts is CaCl2 @ 14.8 ppg. CaCl2 @ 12.4 ppg for including the cacCl2 @ 12.4 ppg for including the caCl2 @ 12.4 ppg for including the ca	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has run intermediate csg. Failed. Spot 300 sks in. Got approval to plug back & sidetrack. Is 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ Circ 225 sks to surface. Plug down @ ok. Test csg to 1500# for 30 mins ok. gged well w/ Halliburton. Ran 182 jts urface. Cmt'd 2 nd stage w/ 600 sks Cl C @ ollowed by 200 sks Cl C + 1% CaCl2 @ RECEIVED OCD - ARTESIA
If the proposal is to deepen dir Attach the Bond under which following completion of the in testing has been completed. F determined that the site is read neediate Csg — Drld 11" hole mt plug. Re-drill 11" secti- 00 sks Cl C Neat cmt plug. ks C 65:35 POZ @ 12.8 p hrs 09/15/06. WOC 24 hrs Production Csg — Drld 7-7/ 15.5# & 17# J-55 csg. Cm pg. Circ 60 sks to surface. pg. Circ 62 sks to surface. 14. Thereby certify that the fore Name (Printed/Typed) Cathy Wright	rectionally or recomplete horizontally, give subsurfathe work will be performed or provide the Bond Nonvolved operations. If the operation results in a multinal Abandonment Notices shall be filed only after thy for final inspection.) The to 4185'. TD reached @ 05:00 hrs on of hole. Attempted to run internounce and the performed by 200 sks C1 "C" + 195. Make cut-off. Install WH. NU Entry hole to 8250'. TD reached @ 2 ant'd 1st stage w/ 600 sks C1 C @ 14. Cmt'd 3rd stage w/ 300 sks C1 C 65. Test csg to 3000# ok. Ran CBL 10 egoing is true and correct	ce locations and measured and true on file with BLM/BIA. Require iple completion or recompletion in all requirements, including reclama is 08/11/06. Attempt to a mediate csg. Failed agai on 09/14/06. Ran 96 jts is CaCl2 @ 14.8 ppg. CaCl2 @ 12.4 ppg for including the cacCl2 @ 12.4 ppg for including the caCl2 @ 12.4 ppg for including the ca	e vertical depths of all pertinent markers and zones. ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has run intermediate csg. Failed. Spot 300 sks in. Got approval to plug back & sidetrack. Is 8-5/8" 32# J-55 LT&C csg. Cmt'd w/ Circ 225 sks to surface. Plug down @ ok. Test csg to 1500# for 30 mins ok. gged well w/ Halliburton. Ran 182 jts urface. Cmt'd 2 nd stage w/ 600 sks Cl C @ ollowed by 200 sks Cl C + 1% CaCl2 @ RECEIVED OCD - ARTESIA