P. 01/01

Submit 3 Copies To Appropriate District	State of New Mo	xico	Form C-103
Office District (ergy, Minerals and Natu	ral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		20.0	L API NO. 15-24156
District II 1301 W. Grand Ave., Artesia, NM 88210	Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION 111 1220 South St. Francis Dr.		dicate Type of Lease
District III			STATE S FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District, IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fc, NM 87	7505 6. S	tate Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCII PROPOSALS.)			Mexico Z State
1. Type of Well: Oil Well Gas Well Other			
2. Name of Operator Mack Energy Corporation			GRID Number 37
3. Address of Operator		1 -	Pool name or Wildcat
PO Box 960 Artesia, NM 88211-0960		Mills	nan;Yates-SR QN-GB-SA, East
4. Well Location			
Unit LetterA:	660feet from theNorth		
Section 12	Township 195		PM County Eddy
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	发表的主张 不是的主体。例
Pit or Below-grade Tank Application and	3378' GR		
	terDistance from nearest fresh w	ater well Distance fro	m nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Constructi	· ·
	ppropriate Box to Indicate N		
12. Check A	ppropriate Box to materie No	ature or Notice, Repor	to other Data
NOTICE OF IN	TENTION TO:		JENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or compl	eted operations. (Clearly state all p	ertinent details, and give	pertinent dates, including estimated date
of starting any proposed wor or recompletion.	k). SEE RULE 1103. For Multipl	e Completions: Attach we	ellbore diagram of proposed completion
7/27/05 5 5 1/27/21/07/20 27147	/281 . A .//1.//		
7/27/05 Set 5-1/2" CIBP @ 1714', cap w/ 35' cmt. w/ bailer. 7/27/05 Circulate hole w/ MLF.			
7/27/05 Spot 35 sx. cmt. @ 465', tag plug @ 130'.			
7/27/05 Spot 10 sx. cmt. from 60' to			
7/28/05 RDMO. Cut off wellhead & a	anchors, install dry hole marker, and	d clean location.	
			·
I hereby certify that the information a grade tank has been/will be constructed or c	bove is true and complete to the bestored according to MMOCD guidelines	st of my knowledge and b	elief. I further certify that any pit or below- trached) alternative OCD-approved plun
SIGNATURE	Ma.		
SIGNATURE TY	TIT'LE_	_Agent	DATE8/3/05
Type or print name Roger Massey For State Use Only	E-mail address:		Telephone No. (432) 530-0907
g end	Jun	Gerry Guye	· • • • 2007
APPROVED BY:	TITLE	Deputy Field Inspect	OT



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor



Joanna Prukep Cabinet Secretary **Acting Director** Oil Conservation Division

29 August 2005

Mack Energy Corp. P. O. Box 960 Artesia, New Mexico 88221-0960

Form C-103 Report of Plugging for your New Mexico State # 1 A-12-19-28 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

1. All pits have been closed as per Rule 50.
2. Rat hole and cellar have been filled and leveled.
3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
5. The dead men and tie downs have been cut and removed.
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
All environmental concerns have been addressed as per OCD guidelines.
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and

Gray W. Shenell 12.20-06
Production Clerk Approval Granted for Final Plug of Well

bore. Bond may be released.

Oil Conservation Division * 1220 South St. Francis Dive Sauce 10, 1207 12. Phone: (505) 476-3440 * Fax (505) 476-3462 * http://www.emard.state.nm.us